

Steinberg UR242 Firmware V1.01 Release Notes

Contents

Main Revisions and Enhancements

Main Revisions and Enhancements

V1.00 to V1.01

- Fixed a problem in which the [POWER] indicator would flash continuously in Windows 10.

Company and product names that appear in this document are the trademarks or registered trademarks of their respective companies.

Manual Development Group
© 2014 Yamaha Corporation
Published 11/2017 YJ-A0

Steinberg UR242 ファームウェア V1.01 リリースノート

目次

主なアップデートの内容

主なアップデートの内容

V1.00 → V1.01

- Windows10 で使用した場合、[POWER]インジケータが点滅し続ける場合がある不具合を修正しました。

本文に掲載されている会社名および商品名等は、各社の登録商標または商標です。

Manual Development Group
© 2017 Yamaha Corporation
2017年11月 発行 YJ-A0