

Steinberg AXR4 Firmware V1.10 Release Notes

Main Revisions and Enhancements

V1.00 to V1.10

- Now supports SRC (Sample Rate Converter).
- Changed operation so that phantom power of a linked channel (for which phantom power is set to on) is turned off when turning channel linking on.
- Changed the position of the headphone outputs from post fader to pre fader on the output bus.
- Moved the HPF cutoff frequency setting from the CH SETUP screen to the SYSTEM SETUP screen.
- Solved a problem in which no sound comes out after inserting an effect to the INSERT SLOT2 of the output channel.
- Solved a problem in which no sound comes out after turning direct monitoring on while the fader of the input channel from the DAW is at $-\infty$ on the dspMixFx AXR.
- Solved a problem in which the headphone outputs may be changed to monaural when turning channel linking on or off.
- Solved a problem in which the sound might not be output properly when turning SOLO off.
- Solved a problem in which the channels being set by the MAIN OUT VOLUME are not changed properly when changing the DIGITAL I/O mode.
- Solved a problem in which a "Duplicated STACK ID" error message may not be displayed after initializing stacked multiple AXR4Ts.
- Solved a problem in which the word clock of the slave AXR4T does not follow the word clock master while AXR4Ts are stacked.
- Solved a problem in which the latency values on the DAW are not displayed correctly.

Company and product names that appear in this document are the trademarks or registered trademarks of their respective companies.

Manual Development Group
© 2019 Yamaha Corporation

Published 02/2019 YJHH-A0

Steinberg AXR4 ファームウェア V1.10 リリースノート

主なアップデートの内容

V1.00 → V1.10

- SRC に対応しました。
- ファンタム電源がオンになっているチャンネルをチャンネルリンクすると、ファンタム電源がオフになるように変更しました。
- ヘッドホン出力の位置を出力バスのポストフェーダーからプリフェーダーに変更しました。
- ハイパスフィルターのカットオフ周波数の設定を CH SETUP 画面から SYSTEM SETUP 画面に移動しました。
- 出力チャンネルの INSERT SLOT2 にエフェクトをインサートすると音が出なくなる問題を修正しました。
- dspMixFx AXR で、DAW からの入力チャンネルのフェーダーを $-\infty$ にしているときにダイレクトモニタリングをオンにすると音が出なくなる問題を修正しました。
- チャンネルリンクを変更したとき、ヘッドホン出力がモノラルになることがある問題を修正しました。
- ソロをオフにしたとき、音が正しく出力されないことがある問題を修正しました。
- デジタル I/O モードを変更したとき、MAIN OUT VOLUME 設定対象のチャンネルが正しく更新されない問題を修正しました。
- AXR4T をスタック接続しているとき、複数の AXR4T を初期化すると、Duplicated STACK ID エラーが表示されなくなることがある問題を修正しました。
- AXR4T をスタック接続しているとき、マスター機器のクロック切り替えにスレーブとなっている AXR4T のワードクロックが追従しない問題を修正しました。
- DAW でレイテンシーの値が正しく表示されない問題を修正しました。

本文に掲載されている会社名および商品名等は、各社の登録商標または商標です。

Manual Development Group
© 2019 Yamaha Corporation

2019 年 2 月 発行 YJHH-A0