

## **Steinberg UR44C/UR22C Firmware V1.01 Release Notes**

---

- UR44C and UR22C have the same firmware.
- The update program is “UR-C\_firmware\_V101.exe” for Windows, and “UR-C\_firmware\_V101.app” for Mac.

### **Main Revisions and Enhancements**

#### **V1.00 to V1.01**

- Fixed a problem in which the analog input/output might not function during startup on the UR44C.

---

Company and product names that appear in this document are the trademarks or registered trademarks of their respective companies.

Manual Development Group  
©2019 Yamaha Corporation  
Published 09/2019 YJTT-A0

## Steinberg UR44C/UR22C ファームウェア V1.01 リリースノート

---

- UR44C と UR22C のファームウェアは共通です。
- アップデートプログラムは、Windows の場合 UR-C\_firmware\_V101.exe、Mac の場合 UR-C\_firmware\_V101.app をご使用ください。

### 主なアップデートの内容

#### V1.00 → V1.01

- UR44C にて、条件によってはまれに起動時にアナログ音声の入出力ができなくなる不具合を修正しました。

---

本文に掲載されている会社名および商品名等は、各社の登録商標または商標です。

Manual Development Group  
© 2019 Yamaha Corporation  
2019 年 9 月 発行 YJTT-A0