

Steinberg UR44 Firmware V2.12 Release Notes

Contents

Main Revisions and Enhancements

Legacy Updates

Main Revisions and Enhancements

V2.11 to V2.12

- Fixed a problem in which the [POWER] indicator would flash continuously in Windows 10.

Legacy Updates

V2.10 to V2.11

- Fixed a problem which the device function does not work properly in a computer running Microsoft Lync 2013 when the CC mode is on.
- Solved some minor problems.

V2.00 to V2.10

- Now supports dspMixFx for iPad.
- Added automatic iPad/computer detection in CC mode so that a computer can also be used.
- ※TOOLS for UR44 V2.1.0 or later is required for use.

V1.00 to V2.00

- Added four Guitar Amp Classics effects to the DSP insert effect.
- ※TOOLS for UR44 V2.0.0 or later is required for use.

Company and product names that appear in this document are the trademarks or registered trademarks of their respective companies.

Steinberg UR44 ファームウェア V2.12 リリースノート

目次

主なアップデートの内容

過去のアップデートの内容

主なアップデートの内容

V2.11 → V2.12

- Windows10 で使用した場合、[POWER]インジケーターが点滅し続ける場合がある不具合を修正しました。

過去のアップデートの内容

V2.10 → V2.11

- Microsoft Lync 2013 が起動しているコンピューターで、CC モードをオンにすると本体の機能が動作しない不具合を修正しました。
- その他の軽微な不具合を修正しました。

V2.00 → V2.10

- iPad 版 dspMixFx に対応しました。
 - CC モードが ON のとき、コンピューターを自動判別して、iPad 以外のコンピューターも使用できるようになりました。
- ※TOOLS for UR44 を V2.1.0 以降にアップデートしてご使用ください。

V1.00 → V2.00

- DSP インサートエフェクトに Guitar Amp Classics 4 種類を追加しました。
- ※ TOOLS for UR44 を V2.0.0 以降にアップデートしてご使用ください。

本文に掲載されている会社名および商品名等は、各社の登録商標または商標です。