

TOOLS for UR824 V1.0.4 for Mac Release Notes

TOOLS for UR824 V1.0.4 for Mac consists of the following programs.

- Yamaha Steinberg USB Driver V1.6.0
- Steinberg UR824 Applications V1.0.4

Steinberg UR824 Applications V1.0.4 consists of the following programs.

- Steinberg UR824 Extension V1.0.4
- Steinberg dspMixFx UR824 V1.0.4
- VST Plug-Ins V1.0.1

Contents

[System Requirements for Software](#)

[Main Revisions and Enhancements](#)

[Legacy Updates](#)

System Requirements for Software

NOTE

- Note that the system requirements may be slightly different from those described below depending on the particular operating system.

OS	Mac OS X 10.5.8/Mac OS X 10.6.x/Mac OS X 10.7.x
CPU	Intel processor (Intel Core Duo CPU recommended)
Memory	1GB or more
Display Resolution	1280 x 800—full color
Interface	Equipped with a USB connector
Hard Disk	Free disk space of 800MB or more; high-speed hard disk
Other	Cubase version 5.5 or later when using the link function between the device and Cubase.

Main Revisions and Enhancements

V1.0.2 to V1.0.4

The main fixes and enhancements for each program are explained below.

Steinberg UR824 Extension

V1.0.1 to V1.0.4

- Now supports Cubase 6.5.

Steinberg dspMixFx UR824

V1.0.1 to V1.0.4

- Solved the problem in which the update program would not work properly without quitting the dspMixFx UR28M when updating the software version with “Check for Update” function on Mac OS X 10.7.

Legacy Updates

V1.0.1 to V1.0.2

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.5.2 to V1.6.0

- Now supports Yamaha 01V96i.

To remove the Yamaha Steinberg USB Driver, delete the following files from the boot disk as well as the files described in the “Uninstalling the Software” section of the Getting Started document.

/Library/Audio/MIDI Devices/Yamaha/Images/

USB_1506.tiff

USB_1507.tiff

USB_5500.tiff

V1.0.0 to V1.0.1

- Now supports Mac OS X 10.7.

The other main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.5.1 to V1.5.2

- Improved audio input and output performance.
- Solved the problem in which the Enable Power Management setting might not be displayed properly when opening the control panel of the driver on Mac OS X 10.6.8 or later (Mac OS X 10.6.7 or later on Mac with Thunderbolt port).

Steinberg UR824 Extension

V1.0.0 to V1.0.1

- Solved the problem in which the initial settings of the Channel Strip would be initialized on the undisturbed channels of increased/decreased channels by switching the sample rate.
- Solved the problem in which the Channel Strip might not work properly when switching the active project in Cubase.
- Solved the problems which would occur when both the UR824 Extension and the MR Extension were being installed. If you use the Steinberg MR816 CSX/MR816 X, download and install the TOOLS for MR V1.7.2 or later from the Steinberg web site.
- Solved some other minor problems.

Steinberg dspMixFx UR824

V1.0.0 to V1.0.1

- Solved some minor problems.

VST Plug-Ins

V1.0.0 to V1.0.1

- Solved some minor problems.

Company and product names that appear in this document are the trademarks or registered trademarks of their respective companies.

(C) 2011-2012 Yamaha Corporation All Rights Reserved.