

TOOLS for UR824 V1.0.4 for Windows Release Notes

TOOLS for UR824 V1.0.4 for Windows consists of the following programs.

- Yamaha Steinberg USB Driver V1.6.2
- Steinberg UR824 Applications V1.0.4

Steinberg UR824 Applications V1.0.4 consists of the following programs.

- Steinberg UR824 Extension V1.0.4
- Steinberg dspMixFx UR824 V1.0.4
- VST Plug-Ins V1.0.1

Contents

[System Requirements for Software](#)

[Main Revisions and Enhancements](#)

[Legacy Updates](#)

System Requirements for Software

NOTE

- Note that the system requirements may be slightly different from those described below depending on the particular operating system.

OS	Windows XP Professional SP3/Windows XP Home Edition SP3/ Windows Vista SP2 (32-bit/64-bit)/ Windows 7 SP0/SP1 (32-bit/64-bit)
CPU	Pentium/Athlon 2GHz or faster (dual core processor recommended)
Memory	1GB or more (2GB or more on Windows 7 64-bit)
Display Resolution	1280 x 800—full color
Interface	Equipped with a USB 2.0 connector
Hard Disk	Free disk space of 800MB or more; high-speed hard disk
Other	Cubase version 5.5 or later when using the link function between the device and Cubase.

Main Revisions and Enhancements

V1.0.3 to V1.0.4

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.6.1 to V1.6.2

- Improved the performance.

Steinberg UR824 Extension

V1.0.1 to V1.0.4

- Now supports Cubase 6.5.

Steinberg dspMixFx UR824

V1.0.1 to V1.0.4

- Solved the problem in which the update program would not work properly with the "Program Compatibility Assistant" dialog, which appears when updating the version of the software and the firmware of the device with the "Check for Update" function on Windows Vista or Windows 7.

Legacy Updates

V1.0.2 to V1.0.3

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.6.0 to V1.6.1

- Solved a problem related to computers equipped with certain AMD brand CPUs, in which noise might occur in the audio input signal when using the device with such a computer.

Steinberg UR824 Applications

V1.0.1 to V1.0.2

- Solved the problem in which certain files would not be properly replaced by new ones when updating the TOOLS for UR824 from V1.0.0.

V1.0.1 to V1.0.2

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.5.2 to V1.6.0

- Now supports Yamaha 01V96i.

- Solved the problem in which the audio input/output might stop when switching the sample rate in the Cubase project setup.
- Solved some other minor problems

V1.0.0 to V1.0.1

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.5.1 to V1.5.2

- Solved some minor problems.

Steinberg UR824 Extension

V1.0.0 to V1.0.1

- Solved the problem in which the initial settings of the Channel Strip would be initialized on the undisturbed channels of increased/decreased channels by switching the sample rate.
- Solved the problem in which the Channel Strip might not work properly when switching the active project in Cubase.
- Solved the problems which would occur when both the UR824 Extension and the MR Extension were being installed. If you use the Steinberg MR816 CSX/MR816 X, download and install the TOOLS for MR V1.7.2 or later from the Steinberg web site.
- Solved some other minor problems.

Steinberg dspMixFx UR824

V1.0.0 to V1.0.1

- Solved some minor problems.

VST Plug-Ins

V1.0.0 to V1.0.1

- Solved some minor problems.

Company and product names that appear in this document are the trademarks or registered trademarks of their respective companies.

(C) 2011-2012 Yamaha Corporation All Rights Reserved.