

MR816 Firmware V1.10 Release Notes

Main Revisions and Enhancements

V1.00 to V1.10

- Operation is improved so that the master level and the headphone level can be adjusted independently. In version 1.00, changing the master level also affected the headphone level because the headphone level was located after the master level in the signal flow. In version 1.10, both levels can be adjusted independently because the signal flow has been modified.

Company and product names that appear in this document are the trademarks or registered trademarks of their respective companies.

(C) 2009 Yamaha Corporation All Rights Reserved.