

## Steinberg UR44C/UR22C Firmware V2.01 Release Notes

---

UR44C and UR22C have the same firmware.

To update, install the latest TOOLS for UR-C on your computer and use the Firmware Update function in dspMixFx UR-C.

Refer to the UR-C V2.0 Supplementary Manual for the update procedure.

### Main Revisions and Enhancements

#### V2.00 to V2.01

Fixed a problem causing a delay when synchronizing the UR-C unit's settings to dspMixFx UR-C when it is launched by double-clicking the SCENE file (xxx.UR22C, xxx.UR44C) on a Mac.

### Legacy Updates

#### V1.50, V1.60-V1.62\* to V2.00

The following functions have been added to the Guitar Amp Classics effects.

- Implemented a noise gate.
- You can now choose from eight types of simulated speaker cabinets.
- You can now select the position of the virtual microphone for placement in front of the cabinet from two types, "Center" or "Edge."

\* V1.60 to V1.62 correspond to some internal part changes and have the same functions as V1.50.

#### V1.01 to V1.50

- The following functions have been added to the effect.

##### Sweet Spot Morphing Channel Strip

- Now includes convenient independent On/Off switches for each EQ band.
- Now includes a convenient On/Off switch for the side chain filter.
- Implemented a side chain meter.
- Implemented an INPUT meter.

##### Guitar Amp Classics

- Implemented an INPUT meter.

##### REV-X

- Implemented INPUT/OUTPUT meters.

- Added a new Voice Chat mode to the Loopback function of the UR-C hardware to optimize use with chat applications.
- Fixed a bug in which MIDI clock was not output from MIDI OUT of the UR-C unit even if

"Send MIDI Clock" was turned on in Cubasis.

- Fixed a bug in which noise was added to the playback sound when switching between Cubasis Background/Foreground when the Cubasis "Background Audio" setting was off.
- Extended the mute time when changing the sample rate. This was done because noise may occur when playing audio from an iPad/iPhone application if the sample rate was changed.
- Fixed a bug in which the dspMixFx UR-C may not be synchronized with the main unit parameters when starting dspMixFx UR-C while inputting MIDI CLOCK from the MIDI terminal.
- Fixed other minor bugs.

#### **V1.00 to V1.01**

- Fixed a problem in which the analog input/output might not function during startup on the UR44C.

---

Company and product names that appear in this document are the trademarks or registered trademarks of their respective companies.

©2019 Yamaha Corporation  
Published 09/2022

## Steinberg UR44C/UR22C ファームウェア V2.01 リリースノート

---

UR44C と UR22C のファームウェアは共通です。

アップデートするには、最新版のTOOLS for UR-CをコンピュータにインストールしてdspMixFx UR-Cのファームウェアアップデート機能を使ってください。

アップデート手順は UR-C V2.0 追補マニュアルをご参照ください。

### 主なアップデートの内容

#### V2.00 → V2.01

Mac 上で SCENE ファイル( xxx.UR22C, xxx.UR44C )をダブルクリックして dspMixFx UR-C を起動したときに、UR-C 本体と dspMixFx UR-C の設定の同期に時間がかかる場合がある不具合を修正しました。

### 過去のアップデートの内容

#### V1.50, V1.60～V1.62\* → V2.00

エフェクト Guitar Amp Classics に以下の機能を追加しました。

- ゲート機能を追加しました
- シミュレートされたスピーカーキャビネットを8種類から選択できるようになりました。
- スピーカーキャビネットに立てるマイクの位置のシミュレーションを Center/Edge の2種類から選択できるようになりました。

\*V1.60～V1.62 は内部の一部の部品変更への対応であり機能は V1.50 と同じです。

#### V1.01 → V1.50

- エフェクトに以下の機能を追加しました。

Sweet Spot Morphing Channel Strip

- EQ の各バンドを個別に ON/OFF できるようになりました。
- サイドチェーンフィルターの ON/OFF ができるようになりました。
- サイドチェーンメーターを追加しました。
- INPUT メーターを追加しました。

Guitar Amp Classics

- INPUT メーターを追加しました。

REV-X

- INPUT/OUTPUT メーターを追加しました。

- ループバック機能に、ボイスチャットアプリケーションの使用時に最適化したボイスチャットモードを追加しました。

- Cubasis で”Send MIDI Clock”をオンしても UR-C 本体の MIDI OUT から MIDI Clock が出力されない不具合を修正しました。
- Cubasis の"Background Audio"の設定がオフの時、Cubasis の Background/Foreground 切り替え時に再生音にノイズが発生する不具合を修正しました。
- iPad/iPhone のアプリケーションからの音声再生時にサンプルレートを変更すると、ノイズが発生することがあったため、サンプルレート変更時のミュート時間を延ばしました。
- MIDI 端子から MIDI CLOCK を入力しているときに、dspMixFx UR-C を起動すると、本体パラメーターと同期がとれないことがある不具合を修正しました。
- その他、軽微な不具合を修正しました。

## **V1.00 → V1.01**

UR44C にて、条件によってはまれに起動時にアナログ音声の入出力ができなくなる不具合を修正しました。

---

本文に掲載されている会社名および商品名等は、各社の登録商標または商標です。

© 2019 Yamaha Corporation  
2022 年 9 月 発行