

# Steinberg UR22mkII Firmware V1.04 Release Notes

---

## Contents

Main Revisions and Enhancements

Legacy Updates

## Main Revisions and Enhancements

### V1.03 to V1.04

- Fixed a problem in which data loss would occur when a large quantity of MIDI data was sent from a computer.

## Legacy Updates

### V1.02 to V1.03

- Fixed a problem that would occur during both audio recording and playback in iOS 10.

### V1.01 to V1.02

- (Mac only) Fixed a problem in which the UR22mkII cannot be recognized on OSX 10.11.
- (Windows only) Improved the performance stability of the UR22mkII when a connected computer would return to normal operation from sleep mode.

### V1.00 to V1.01

- (Windows only) Fixed a problem which MIDI communication was unavailable between the UR22mkII and an application (Cubase, etc.) when a computer would return to normal operation from sleep mode.  
※Yamaha Steinberg USB Driver V1.9.6 or later is required for use on Windows.

---

Company and product names that appear in this document are the trademarks or registered trademarks of their respective companies.

(C) 2015-2016 Yamaha Corporation.

# Steinberg UR22mkII ファームウェア V1.04 リリースノート

---

## 目次

主なアップデートの内容

過去のアップデートの内容

## 主なアップデートの内容

### V1.03 → V1.04

- コンピューターから大量の MIDI データを送信する時にデータが欠けることがある問題を修正しました。

## 過去のアップデートの内容

### V1.02 → V1.03

- iOS 10 環境で、オーディオ録音および再生時に不具合が発生する問題を修正しました。

### V1.01 → V1.02

- (Mac のみ) OS X 10.11 で認識されないことがある問題を修正しました。
- (Windows のみ) コンピューターがスリープモードから復帰したときの UR22mkII の動作安定性を向上しました。

### V1.00 → V1.01

- (Windows のみ) コンピューターがスリープモードから復帰したときに、MIDI を扱うアプリケーション(Cubase 等) と UR22mkII とで MIDI 通信ができなくなる不具合を修正しました。

※Windows 環境でお使いの場合は、Yamaha Steinberg USB Driver を V1.9.6 以降にアップデートしてご使用ください。

---

本文に掲載されている会社名および商品名等は、各社の登録商標または商標です。

(C) 2015-2016 Yamaha Corporation.