

Yamaha Steinberg USB Driver V1.6.0 for Mac Release Notes

Contents

[System Requirements for Software](#)

[Main Revisions and Enhancements](#)

[Legacy Updates](#)

System Requirements for Software

NOTE

Note that the system requirements may be slightly different from those described below depending on the particular operating system.

OS	Mac OS X 10.5.8/Mac OS X 10.6.x/Mac OS X 10.7x
CPU	Intel processor (Intel Core Duo CPU recommended)
Memory	1GB or more
Interface	Equipped with a USB connector
Hard Disk	Free disk space of 50MB or more; high-speed hard disk

Main Revisions and Enhancements

V1.5.2 to V1.6.0

- Now supports Yamaha 01V96i.

To remove the Yamaha Steinberg USB Driver, delete the following file from the boot disk as well as described files in the “Uninstalling the Software” section of the Yamaha Steinberg USB Driver Installation Guide.

/Library/Audio/MIDI Devices/Yamaha/Images/

USB_5500.tiff

Legacy Updates

V1.5.1 to V1.5.2

- Now supports Mac OS X 10.7.
- Improved audio input and output performance.
- Solved the problem in which applications such as DAW software might not work because the lead-off MIDI data would not be sent/received properly after second launching of the

applications on Mac OS X 10.6.8 or later (Mac OS X 10.6.7 or later on Mac with Thunderbolt port).

V1.5.0 to V1.5.1

- Now supports Steinberg UR824.
- Solved some minor problems.

NOTE

Yamaha Steinberg USB Driver V1.5.1 is the version which is included in the TOOLS for UR824 CD-ROM (labeled "YD307A0") in the Steinberg UR824 package.

V1.3.0 to V1.5.0

- Now supports Steinberg UR28M.
- Solved some minor problems.

NOTE

Yamaha Steinberg USB Driver V1.5.0 is the version which is included in the TOOLS for UR28M CD-ROM (labeled "YD304A0") in the Steinberg UR28M package.

V1.2.0 to V1.3.0

- Now supports Yamaha MOX6/8.
- Solved the problem in which noise would occasionally occur during playback in a specific condition when using a device compatible with the Yamaha Steinberg USB Driver on Mac computer with an Intel processor and Mac OS X 10.6.5 or later.

V1.1.1 to V1.2.0

- Now supports 64-bit kernel of Mac OS X 10.6.
- Changed the system requirements to the following.
 - Mac OS X 10.5.8 or 10.6.x
 - Mac computer with an Intel processor

For details, refer to the "[System Requirements for Software.](#)"

- Solved the problem in which noise would occasionally occur during playback when using a device compatible with the Yamaha Steinberg USB Driver on Mac computer with an Intel processor and Mac OS X 10.6.5 or later.

V1.1.0 to V1.1.1

- Improved the stability of Yamaha Steinberg USB Driver on a Mac with an Intel Core i series processor.
- Improved the following problems.
 - When using a device compatible with Yamaha Steinberg USB Driver on a Mac with an Intel Core i series processor, recorded audio data might be briefly interrupted.
 - When using a device compatible with Yamaha Steinberg USB Driver on a Mac with an Intel Core i series processor, noise may occasionally occur when playback starts.

V1.0.1 to V1.1.0

- Now supports Steinberg CI1 and Steinberg CI2+.

V1.0.0 to V1.0.1

- Yamaha Steinberg USB Driver now supports Mac OS X 10.6.

Company and product names that appear in this document are the trademarks or registered trademarks of their respective companies.

(C) 2010-2011 Yamaha Corporation All Rights Reserved.