

TOOLS for UR824 V2.2.0 for Windows Release Notes

TOOLS for UR824 V2.2.0 for Windows consists of the following programs.

- Yamaha Steinberg USB Driver V1.10.3
- Steinberg UR824 Applications V2.2.0
- Basic FX Suite V1.1.1

Steinberg UR824 Applications V2.2.0 consists of the following programs.

- Steinberg UR824 Extension V2.1.6
- Steinberg dspMixFx UR824 V2.2.0

Contents

[System Requirements for Software](#)

[Main Revisions and Enhancements](#)

[Legacy Updates](#)

System Requirements for Software

NOTE

- Note that the system requirements may be slightly different from those described below depending on the particular operating system.

OS	Windows 7 SP1/Windows 8.1/Windows 10
CPU	Intel/AMD dual core processor or higher
Memory	2 GB or more
Interface	Equipped with a USB 2.0 connector
Hard Disk	Free disk space of 1.2 GB or more; high-speed hard disk
Other	<ul style="list-style-type: none">- UR824 Firmware V2.10 or later- When using the link function between the device and Cubase, Cubase 8 series software or later: 8.0 or later

Main Revisions and Enhancements

V2.1.6 to V2.2.0

- Changed the system requirements to the following.
Cubase 8.0 version or later

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.9.11 to V1.10.3

- Fixed a problem in which noise might occur in the input/output when the ASIO buffer size was set to small value..
- Fixed a problem that application software would become unusable when recovering from sleep mode on a Modern Standby compatible PC.
- Now supports Yamaha MODX series.
- Solved a problem in which an application which uses Yamaha Steinberg USB Driver might be stopped when starting the application after a Windows update, etc.
- Solved a problem in which audio drop out may occur in some environments.
- Solved a problem in which noise may occur in a certain environment.
- Added a selection of 32 samples to the buffer size setting of the ASIO driver.
- Solved some other minor problems.

Steinberg UR28M Applications

V2.1.6 to V2.2.0

- Deleted the check for update function for dspMixFX.

Basic FX Suite

V1.0.1 to V1.1.1

- Improved the display in Windows 10.

Legacy Updates

V2.1.5 to V2.1.6

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.9.9 to V1.9.11

- Now supports Yamaha EAD10.

Steinberg UR824 Extension

V2.1.5 to V2.1.6

- Solved some minor problems.

V2.1.4 to V2.1.5

The main fixes and enhancements for each program are explained below.

Steinberg UR824 Extension

V2.1.2 to V2.1.5

- Solved some minor problems.

V2.1.3 to V2.1.4

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.9.5 to V1.9.9

- Solved some minor problems on the UR22mkII.
- Solved a problem in which the Yamaha Steinberg USB Driver would not work in certain cases on the AUDIOGRAM/ MW/ MG/ IM series.
- Solved the following problems.
 - Audio loss may occur depending on the user environment.
 - Audio may distort after some period of time.
- Now supports Yamaha MONTAGE.
- Solved some minor problems.

V2.1.2 to V2.1.3

Now supports Windows 10.

Yamaha Steinberg USB Driver

V1.9.2 to V1.9.5

Steinberg dspMixFx UR824

V2.1.0 to V2.1.3

V2.1.1 to V2.1.2

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.8.6 to V1.9.2

- Now supports Yamaha AG Series.
- Now supports Yamaha A-S801.

- Solved some minor problems.

Steinberg UR824 Extension

V2.1.0 to V2.1.2

- Solved some minor problems.

Basic FX Suite

V1.0.0 to V1.0.1

- Solved some minor problems.

V2.1.0 to V2.1.1

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.8.5 to V1.8.6

- Now supports Yamaha AUDIOGRAM/ MW/ MG/ IM Series (USB-equipped model).

NOTE

If the Yamaha USB Audio Driver is already installed on your computer, be sure to uninstall it before installing Yamaha Steinberg USB Driver. There is a possibility that the Yamaha Steinberg USB Driver will not work properly if the Yamaha USB Audio Driver is installed on the same computer.

- Now supports Yamaha MOXF Series firmware V1.10.
- Solved some minor problems.

V2.0.1 to V2.1.0

- Now supports UR824 Firmware V2.10.

The other main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.8.4 to V1.8.5

- Now supports UR824 Firmware V2.10.

V1.8.3 to V1.8.4

- Now supports Yamaha MG Series (XU Models).

Steinberg UR824 Extension

V2.0.0 to V2.1.0

- Added the project templates for Cubase.

V2.0.0 to V2.0.1

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.8.1 to V1.8.3

- Now supports Windows 8.1.
- Solved some minor problems.

V1.8.0 to V1.8.1

- Now supports Yamaha MOXF6/8.
- Solved some minor problems.

V1.5.0 to V2.0.0

- Added four Guitar Amp Classics effects to the DSP insert effect.
- Added the Loopback function.
- Restructured the VST Plug-ins as Basic FX Suite.
- Changed the system requirements to the following.
Windows 7 or Windows 8

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.7.3 to V1.8.0

- Now supports Yamaha CD-S3000
- ASIO Driver supports devices which use 32-bit sample format.
- Solved some minor problems.

Steinberg UR824 Extension

V1.5.0 to V2.0.0

- Added the project templates for Cubase 7.

Steinberg dspMixFx UR824

V1.5.0 to V2.0.0

V1.0.6 to V1.5.0

- Added the 176.4 kHz and 192 kHz settings to the sample rate selection.
For details on setting the sample rate and limits regarding higher settings, refer to the latest manuals downloadable from the Steinberg website.
※UR824 Firmware V1.50 or later is required for use.

The other main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.7.2 to V1.7.3

- Fixed a problem in which noise would occur during audio playback with the WDM.

V1.0.5 to V1.0.6

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.7.1 to V1.7.2

- Now supports Cubase 7.
- Solved some minor problems.

V1.6.5 to V1.7.1

- Now supports Steinberg UR22.

NOTE

Yamaha Steinberg USB Driver V1.7.1 is the version which is included in the TOOLS for UR22 CD-ROM (labeled "YE968B0") in the Steinberg UR22 package.

Steinberg UR824 Extension

V1.0.4 to V1.0.6

Steinberg dspMixFx UR824

V1.0.5 to V1.0.6

- Now supports Cubase 7.

V1.0.4 to V1.0.5

- TOOLS for UR824 has been confirmed to work properly on Windows 8.

The other main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.6.4 to V1.6.5

- Solved some minor problems.

V1.6.3 to V1.6.4

- Now supports Yamaha MX49/61.
- Solved some minor problems.

V1.6.2 to V1.6.3

- Solved a problem in which the specified DAW software would not quit when switching the sample rate setting.
- Solved some other minor problems.

Steinberg dspMixFx UR824

V1.0.4 to V1.0.5

- Solved some minor problems.

V1.0.3 to V1.0.4

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.6.1 to V1.6.2

- Improved the performance.

Steinberg UR824 Extension

V1.0.1 to V1.0.4

- Now supports Cubase 6.5.

Steinberg dspMixFx UR824

V1.0.1 to V1.0.4

- Solved the problem in which the update program would not work properly with the “Program Compatibility Assistant” dialog, which appears when updating the version of the software and the firmware of the device with the “Check for Update” function on Windows Vista or Windows 7.

V1.0.2 to V1.0.3

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.6.0 to V1.6.1

- Solved a problem related to computers equipped with certain AMD brand CPUs, in which noise might occur in the audio input signal when using the device with such a computer.

Steinberg UR824 Applications

V1.0.1 to V1.0.2

- Solved the problem in which certain files would not be properly replaced by new ones when updating the TOOLS for UR824 from V1.0.0.

V1.0.1 to V1.0.2

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.5.2 to V1.6.0

- Now supports Yamaha 01V96i.
- Solved the problem in which the audio input/output might stop when switching the sample rate in the Cubase project setup.
- Solved some other minor problems

V1.0.0 to V1.0.1

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.5.1 to V1.5.2

- Solved some minor problems.

Steinberg UR824 Extension

V1.0.0 to V1.0.1

- Solved the problem in which the initial settings of the Channel Strip would be initialized on the undisturbed channels of increased/decreased channels by switching the sample rate.
- Solved the problem in which the Channel Strip might not work properly when switching the active project in Cubase.
- Solved the problems which would occur when both the UR824 Extension and the MR Extension were being installed. If you use the Steinberg MR816 CSX/MR816 X, download and install the TOOLS for MR V1.7.2 or later from the Steinberg web site.
- Solved some other minor problems.

Steinberg dspMixFx UR824

V1.0.0 to V1.0.1

- Solved some minor problems.

VST Plug-Ins

V1.0.0 to V1.0.1

- Solved some minor problems.

Company and product names that appear in this document are the trademarks or registered trademarks of their respective companies.

Manual Development Group
© 2011 Yamaha Corporation
Published 11/2018 YJTT-A0

TOOLS for UR824 V2.2.0 for Windows リリースノート

TOOLS for UR824 V2.2.0 for Windows は、以下のプログラムで構成されています。

- Yamaha Steinberg USB Driver V1.10.3
- Steinberg UR824 Applications V2.2.0
- Basic FX Suite V1.1.1

Steinberg UR824 Applications V2.2.0 は、以下のプログラムで構成されています。

- Steinberg UR824 Extension V2.1.6
- Steinberg dspMixFx UR824 V2.2.0

目次

ソフトウェアの動作環境

主なアップデートの内容

過去のアップデートの内容

ソフトウェアの動作環境

NOTE

- お使いの OS によっては、下記の仕様以上の条件を満たす必要があります。

OS	Windows 7 SP1/Windows 8.1/Windows 10
CPU	デュアルコア以上の Intel/AMD プロセッサー
メモリー	2 GB 以上
インターフェース	USB 2.0 端子を搭載していること
ハードディスク	1.2 GB 以上の空き容量、高速なハードディスク
その他	<ul style="list-style-type: none">UR824 のファームウェア: V2.10 以降Cubase との連携機能をお使いの場合、Cubase のバージョン 8.0 以降

主なアップデートの内容

V2.1.6 → V2.2.0

- 動作環境を変更しました。以下の環境が必要です。
Cubase 8.0 以降

その他の主なアップデート内容については、以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.9.11 → V1.10.3

- ASIO バッファーサイズを小さく設定したとき、入出力にノイズが混入することがある問題を修正しました。
- Modern Standby 対応の PC でスリープから復帰したとき、アプリケーションソフトが使用不能になる問題を修正しました。
- Yamaha MODX シリーズに対応しました。
- Windows アップデート後などに Yamaha Steinberg USB Driver を使用するアプリケーションを起動すると、アプリケーションが停止することがある問題を修正しました。
- 一部の環境でオーディオドロップアウトが発生する問題を修正しました。
- 特定の環境でノイズが発生する問題を修正しました。
- ASIO ドライバーのバッファーサイズの設定値に、32 サンプルを追加しました。
- その他の軽微な不具合を修正しました。

Steinberg UR28M Applications

V2.1.6 → V2.2.0

- dspMixFx の Check for Update 機能を削除しました。

Basic FX Suite

V1.0.1 → V1.1.1

- Windows 10 での表示を改善しました。

過去のアップデートの内容

V2.1.5 → V2.1.6

主なアップデート内容については、以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.9.9 → V1.9.11

- Yamaha EAD10 に対応しました。

Steinberg UR824 Extension

V2.1.5 → V2.1.6

- 軽微な不具合を修正しました。

V2.1.4 → V2.1.5

主なアップデート内容については、以下にプログラム別で説明します。

Steinberg UR824 Extension

V2.1.2 → V2.1.5

- 軽微な不具合を修正しました。

V2.1.3 → V2.1.4

主なアップデート内容については、以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.9.5 → V1.9.9

- UR22mkII での軽微な不具合を修正しました。
- AUDIOGRAM/ MW/ MG/ IM シリーズで動作しない場合がある問題を修正しました。
- 以下の問題への対策を行ないました。
 - ・お使いの環境によっては、音が途切れることがある。
 - ・ある一定時間を経過すると音が歪むことがある。
- Yamaha MONTAGE シリーズに対応しました。
- 軽微な不具合を修正しました。

V2.1.2 → V2.1.3

- Windows 10 に対応しました。

Yamaha Steinberg USB Driver

V1.9.2 → V1.9.5

Steinberg dspMixFx UR824

V2.1.0 → V2.1.3

V2.1.1 → V2.1.2

主なアップデート内容については、以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.8.6 → V1.9.2

- Yamaha AG シリーズに対応しました。
- Yamaha A-S801 に対応しました。
- 軽微な不具合を修正しました。

Steinberg UR824 Extension

V2.1.0 → V2.1.2

- 軽微な不具合を修正しました。

Basic FX Suite

V1.0.0 → V1.0.1

- 軽微な不具合を修正しました。

V2.1.0 → V2.1.1

主なアップデート内容については、以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.8.5 → V1.8.6

- Yamaha AUDIOGRAM/ MW/ MG/ IM シリーズの USB 搭載モデルに対応しました。

NOTE

Yamaha USB Audio Driver がコンピューターにインストールされている場合は、アンインストールしてから Yamaha Steinberg USB Driver をインストールしてください。同時にインストールされている場合、Yamaha Steinberg USB Driver が使用できない場合があります。

- Yamaha MOXF シリーズ ファームウェア V1.10 に対応しました。

- 軽微な不具合を修正しました。

V2.0.1 → V2.1.0

- 本体ファームウェア V2.10 に対応しました。

その他の主なアップデート内容については、以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.8.4 → V1.8.5

- 本体ファームウェア V2.10 に対応しました。

V1.8.3 → V1.8.4

- Yamaha MG シリーズ(XU モデル)に対応しました。

Steinberg UR824 Extension

V2.0.0 → V2.1.0

- Cubase 用のプロジェクトテンプレートを追加しました。

V2.0.0 → V2.0.1

主なアップデート内容については、以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.8.1 → V1.8.3

- Windows 8.1 に対応しました。
- 軽微な不具合を修正しました。

V1.8.0 → V1.8.1

- Yamaha MOXF6/8 に対応しました。
- 軽微な不具合を修正しました。

V1.5.0 → V2.0.0

- DSP インサートエフェクトに Guitar Amp Classics 4 種類を追加しました。
- ループバック機能を追加しました。
- VST プラグインを Basic FX Suite として再構成しました。
- 動作環境を変更しました。以下の環境が必要です。

Windows 7 SP1 または Windows 8

その他の主なアップデート内容については、以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.7.3 → V1.8.0

- Yamaha CD-S3000 に対応しました。
- ASIO ドライバーが、32bit のサンプルフォーマットを使用する機器に対応しました。
- 軽微な不具合を修正しました。

Steinberg UR824 Extension

V1.5.0 → V2.0.0

- Cubase7 用のプロジェクトテンプレートを追加しました。

Steinberg dspMixFx UR824

V1.5.0 → V2.0.0

V1.0.6 → V1.5.0

- サンプリング周波数を 176.4 kHz/192 kHz に設定できるようになりました。
サンプリング周波数の切り替え方法や制限事項などの詳細は、スタンバーグのウェブサイトからダウンロードできる最新の取扱説明書をご参照ください。
※UR824 のファームウェアを V1.50 以降にアップデートしてご使用ください。

その他の主なアップデート内容については、以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.7.2 → V1.7.3

- WDM を利用してオーディオを再生した場合、ノイズが発生することがある問題を修正しました。

V1.0.5 → V1.0.6

以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.7.1 → V1.7.2

- Cubase 7 に対応しました。
- 軽微な不具合を修正しました。

V1.6.5 → V1.7.1

- Steinberg UR22 に対応しました。

NOTE

Yamaha Steinberg USB Driver V1.7.1 は、Steinberg UR22 に同梱の TOOLS for UR22 CD-ROM (盤面に「YE968B0」と記載されているもの)に収録されているバージョンです。

Steinberg UR824 Extension

V1.0.4 → V1.0.6

Steinberg dspMixFx UR824

V1.0.5 → V1.0.6

- Cubase 7 に対応しました。

V1.0.4 → V1.0.5

- TOOLS for UR824 が Windows 8 で動作することを確認しました。

その他の主なアップデート内容については、以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.6.4 → V1.6.5

- 軽微な不具合を修正しました。

V1.6.3 → V1.6.4

- Yamaha MX49/61 に対応しました。
- 軽微な不具合を修正しました。

V1.6.2 → V1.6.3

- 特定の DAW ソフトウェアで使用している場合、サンプリング周波数などの設定を変更したときに DAW ソフトウェアが終了できなくなる問題を修正しました。
- その他の軽微な不具合を修正しました。

Steinberg dspMixFx UR824

V1.0.4 → V1.0.5

- 軽微な不具合を修正しました。

V1.0.3 → V1.0.4

以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.6.1 → V1.6.2

- パフォーマンスを改善しました。

Steinberg UR824 Extension

V1.0.1 → V1.0.4

- Cubase 6.5 に対応しました。

Steinberg dspMixFx UR824

V1.0.1 → V1.0.4

- Windows Vista または Windows 7 で、Check for update 機能にてソフトウェアや本体のファームウェアを新しいバージョンに更新するときに、「プログラム互換性アシスタント」ダイアログが表示され、

更新が正常に行えないことがある問題を修正しました。

V1.0.2 → V1.0.3

以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.6.0 → V1.6.1

- AMD 社製の一部の CPU を搭載したコンピューターで使用したときに、オーディオの入力にノイズが発生するがある問題を修正しました。

Steinberg UR824 Applications

V1.0.1 → V1.0.2

- TOOLS for UR824 V1.0.0 からアップデートしたときに、一部のファイルが新しいものに差し替わらない問題を修正しました。

V1.0.1 → V1.0.2

以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.5.2 → V1.6.0

- Yamaha 01V96i に対応しました。
- Cubase のプロジェクト設定でサンプリング周波数を切り替えると、オーディオ入出力が止まることがある問題を修正しました。
- その他の軽微な不具合を修正しました。

V1.0.0 → V1.0.1

以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.5.1 → V1.5.2

- 軽微な不具合を修正しました。

Steinberg UR824 Extension

V1.0.0 → V1.0.1

- サンプリング周波数を変更して入出力のチャンネル数が変わったときに、増減したチャンネル以外のチャンネルの、Channel Strip の設定も初期化してしまう問題を修正しました。

- プロジェクトを切り替えたときに、Channel Strip が動作しないことがある問題を修正しました。
- MR Extension と UR824 Extension が共にインストールされている際に発生する問題を修正しました。Steinberg MR816 CSX/MR816 X をご使用の場合は、TOOLS for MR V1.7.2 以降をスタンバーグのウェブサイトからダウンロードしてインストールしてください。
- その他軽微な不具合を修正しました。

Steinberg dspMixFx UR824

V1.0.0 → V1.0.1

- 軽微な不具合を修正しました。

VST Plug-Ins

V1.0.0 → V1.0.1

- 軽微な不具合を修正しました。

本文に掲載されている会社名および商品名等は、各社の登録商標または商標です。

Manual Development Group
© 2011 Yamaha Corporation
2018 年 11 月 発行 YJTT-A0