

TOOLS for UR44 V2.2.1 for Mac Release Notes

TOOLS for UR44 V2.2.1 for Mac consists of the following programs.

- Yamaha Steinberg USB Driver V2.0.2
- Steinberg UR44 Applications V2.2.1
- Basic FX Suite V1.1.1

Steinberg UR44 Applications V2.2.1 consists of the following programs.

- Steinberg UR44 Extension V2.1.3
- Steinberg dspMixFx UR44 V2.2.1

System Requirements for Software

NOTE

- Note that the system requirements may be slightly different from those described below depending on the particular operating system.

| | |
|-----------|--|
| OS | macOS 10.12.6, macOS 10.13.6, macOS 10.14.x, macOS 10.15.x |
| CPU | Intel multicore processor (Intel Core i5 or faster recommended) |
| Memory | 2 GB or more |
| Interface | Equipped with a USB connector |
| Hard Disk | Free disk space of 1.2 GB or more; high-speed hard disk |
| Other | <ul style="list-style-type: none">- UR44 Firmware V2.10 or later- Cubase version 8.0 or later when using the link function between the device and Cubase. |

Main Revisions and Enhancements

V2.2.0 to V2.2.1

- Now supports macOS 10.15.
- Changed the system requirements to the following.
macOS 10.12.6, macOS 10.13.6, macOS 10.14.x, macOS 10.15.x
Intel multicore processor (Intel Core i5 or faster recommended)

Yamaha Steinberg USB Driver

V1.10.2 to V2.0.2

- Solved a problem in which USB data transfer could not be completed in time and audio dropout would occur if a Mac with slower USB transfer spec was used with macOS 10.12 or

later.

- Changed the launch method of the control panel. Launched by [Application] → [Yamaha Steinberg USB Control Panel].
- Solved some minor problems.

Legacy Updates

V2.1.3 to V2.2.0

- Changed the system requirements to the following.
Mac OS X 10.11/macOS 10.12/macOS 10.13/macOS 10.14
Cubase 8.0 or later

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.9.10 to V1.10.2

- Now supports Yamaha MODX series

Steinberg UR44 Applications

V2.1.3 to V2.2.0

- Optimized the operation for 64-bit operating systems.
- Deleted the check for update function for dspMixFX.

Basic FX Suite

V1.0.1 to V1.1.0

- Added the AU Plug-ins.

V2.1.2 to V2.1.3

- Changed the system requirements to the following.
OS X 10.9.5/OS X 10.10.5/OS X 10.11.x/macOS 10.12.x

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.9.8 to V1.9.10

- Now supports Yamaha MONTAGE series firmware V1.20.
- Solved some minor problems.
- Now supports Yamaha MONTAGE.

Steinberg UR44 Extension

V2.1.2 to V2.1.3

- Solved some minor problems.

Steinberg dspMixFx UR44

V2.1.2 to V2.1.3

- Solved some minor problems.

V2.1.1 to V2.1.2

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.9.6 to V1.9.8

- Improved audio input and output performance.
- Fixed a problem in which audio drop-outs would occur during both audio recording and playback on OS X 10.11.1.

V2.1.0 to V2.1.1

- Changed the system requirements to the following.
OS X 10.9.5, OS X 10.10.x, OS X 10.11.x

The other main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.9.4 to V1.9.6

- Now supports OS X 10.11.

V1.9.3 to V1.9.4

- Now supports Steinberg UR22mkII.
- Solved some minor problems.

V1.9.2 to V1.9.3

- Now supports Yamaha THR100H/THR100HD.

V1.9.0 to V1.9.2

- Now supports Yamaha AUDIOGRAM/ MW/ MG/ IM Series (USB-equipped model).
- Solved some minor problems.

V1.8.6 to V1.9.0

- Now supports Yamaha A-S801.
- Improved audio input and output performance.

V1.8.5 to V1.8.6

- Now supports Yamaha MOXF series firmware V1.10.

Basic FX Suite

V1.0.0 to V1.0.1

- Solved some minor problems.

V2.0.0 to V2.1.0

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.8.3 to V1.8.5

- Now supports UR44 Firmware V2.10.

Steinberg UR44 Extension

V2.0.0 to V2.1.0

- Now supports UR44 Firmware V2.10.
- Added the project templates for Cubase.

V1.0.1 to V2.0.0

- Added four Guitar Amp Classics effects to the DSP insert effect.
 - ※Firmware V2.0.0 or later is required before using.

V1.0.0 to V1.0.1

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.8.2 to V1.8.3

- Now supports OS X 10.9.

Company and product names that appear in this document are the trademarks or registered trademarks of their respective companies.

Manual Development Group
© 2013 Yamaha Corporation
Published 01/2020 YJTY-A0

TOOLS for UR44 V2.2.1 for Mac リリースノート

TOOLS for UR44 V2.2.1 for Mac は、以下のプログラムで構成されています。

- Yamaha Steinberg USB Driver V2.0.2
- Steinberg UR44 Applications V2.2.1
- Basic FX Suite V1.1.1

Steinberg UR44 Applications V2.2.1 は、以下のプログラムで構成されています。

- Steinberg UR44 Extension V2.1.3
- Steinberg dspMixFx UR44 V2.2.1

ソフトウェアの動作環境

NOTE

- お使いの OS によっては、下記の仕様以上の条件を満たす必要があります。

| | |
|----------|---|
| OS | macOS 10.12.6、macOS 10.13.6、macOS 10.14.x、macOS 10.15.x |
| CPU | Intel マルチコアプロセッサ (Intel Core i5 以上推奨) |
| メモリー | 2 GB 以上 |
| インターフェース | USB 端子を搭載していること |
| ハードディスク | 1.2 GB 以上の空き容量、高速なハードディスク |
| その他 | - UR44 ファームウェア: V2.10 以降 - Cubase との連携機能をお使いの場合、Cubase のバージョン 8.0 以降 |

主なアップデートの内容

V2.2.0 → V2.2.1

- macOS 10.15 に対応しました。
- 動作環境を変更しました。以下の環境が必要です。
macOS 10.12.6、macOS 10.13.6、macOS 10.14.x、macOS 10.15.x
Intel マルチコアプロセッサ (Intel Core i5 以上推奨)

Yamaha Steinberg USB Driver

V1.10.2 → V2.0.2

- USB 転送の遅い Mac を macOS 10.12 以降の新しい OS で使用した場合に、データ転送が間に合わずオーディオドロップアウトが発生する問題を修正しました。
- コントロールパネルの起動方法を変更しました。[アプリケーション] → [Yamaha Steinberg USB Control Panel] で起動します。
- その他の軽微な不具合を修正しました。

過去のアップデートの内容

V2.1.3 → V2.2.0

- 動作環境を変更しました。以下の環境が必要です。
Mac OS X 10.11/macOS 10.12/macOS 10.13/macOS 10.14
Cubase 8.0 以降

その他の主なアップデート内容については、以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.9.10 → V1.10.2

- Yamaha MODX シリーズに対応しました。

Steinberg UR44 Applications

V2.1.3 → V2.2.0

- 64-bit OS での動作を最適化しました。
- dspMixFx の Check for Update 機能を削除しました。

Basic FX Suite

V1.0.1 → V1.1.0

- AU プラグインを追加しました。

V2.1.2 → V2.1.3

- 動作環境を変更しました。以下の環境が必要です。
OS X 10.9.5/OS X 10.10.5/OS X 10.11.x/macOS 10.12.x

その他の主なアップデート内容については、以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.9.8 → V1.9.10

- Yamaha MONTAGE シリーズ ファームウェア V1.20 に対応しました。
- 軽微な不具合を修正しました。
- Yamaha MONTAGE シリーズに対応しました。

Steinberg UR44 Extension

V2.1.2 → V2.1.3

- 軽微な不具合を修正しました。

Steinberg dspMixFx UR44

V2.1.2 → V2.1.3

- 軽微な不具合を修正しました。

V2.1.1 → V2.1.2

主なアップデート内容については、以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.9.6 → V1.9.8

- オーディオ入出力のパフォーマンスを向上しました。
- OS X 10.11.1 環境で、オーディオ録音および再生時に音切れが発生する問題を修正しました。

V2.1.0 → V2.1.1

- 動作環境を変更しました。以下の環境が必要です。

OS X 10.9.5, OS X 10.10.x, OS X 10.11.x

その他の主なアップデート内容については、以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.9.4 → V1.9.6

- OS X 10.11 に対応しました。

V1.9.3 → V1.9.4

- Steinberg UR22mkII に対応しました。
- 軽微な不具合を修正しました。

V1.9.2 → V1.9.3

- Yamaha THR100H/THR100HD に対応しました。

V1.9.0 → V1.9.2

- Yamaha AUDIOGRAM/ MW/ MG/ IM シリーズの USB 搭載モデルに対応しました。
- 軽微な不具合を修正しました。

V1.8.6 → V1.9.0

- Yamaha A-S801 に対応しました。
- オーディオ入出力のパフォーマンスを向上しました。

V1.8.5 → V1.8.6

- Yamaha MOXF シリーズ ファームウェア V1.10 に対応しました。

Basic FX Suite

V1.0.0 → V1.0.1

- 軽微な不具合を修正しました。

V2.0.0 → V2.1.0

主なアップデート内容について、以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.8.3 → V1.8.5

- 本体ファームウェア V2.10 に対応しました。

Steinberg UR44 Extension

V2.0.0 → V2.1.0

- 本体ファームウェア V2.10 に対応しました。
- Cubase 用のプロジェクトテンプレートを追加しました。

V1.0.1 → V2.0.0

- DSP インサートエフェクトに Guitar Amp Classics 4 種類を追加しました。
※ファームウェアを V2.0.0 以降にアップデートしてご使用ください。

V1.0.0 → V1.0.1

主なアップデート内容について、以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.8.2 → V1.8.3

- OS X 10.9 に対応しました。

本文に掲載されている会社名および商品名等は、各社の登録商標または商標です。