

TOOLS for UR44 V2.2.2 for Windows Release Notes

TOOLS for UR44 V2.2.2 for Windows consists of the following programs.

- Yamaha Steinberg USB Driver V2.0.4
- Steinberg UR44 Applications V2.2.2
- Basic FX Suite V1.1.4

Steinberg UR44 Applications V2.2.2 consists of the following programs.

- Steinberg UR44 Extension V2.1.1
- Steinberg dspMixFx UR44 V2.2.0

System Requirements for Software

NOTE

- Note that the system requirements may be slightly different from those described below depending on the particular operating system.

OS	Windows10(64-bit)
CPU	Intel Core i-series multicore processor 2GHz or faster, or AMD equivalent processor
Memory	4 GB
Display Resolution	1280 x 800; full color
Interface	Equipped with a USB connector
Hard Disk	Free disk space of 1.2 GB or more; high-speed hard disk
Other	- UR44 Firmware V2.10 or later - Cubase 9.0 or later when using the link function between the device and Cubase.

Main Revisions and Enhancements

V2.2.1 to V2.2.2

- Changed the system requirements.

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V2.0.3 to V2.0.4

- Now supports Yamaha YDS-150.
- Fixed a problem in which DSD could not be played back with some Yamaha audio devices.

Steinberg UR44 Applications

V2.2.1 to V2.2.2

- Fixed a problem in which the parameter of the bundled plug-in on the Cubase 11 Inspector panel may not be changed by operating a mouse wheel when the magnification of the display setting is other than 100%.

Basic FX Suite

V1.1.2 to V1.1.4

- Solved a problem in which FL Studio would terminate abnormally when a plug-in was inserted in FL Studio.
- Fixed a problem in which a plug-in parameter in Cubase 11 may not be changed properly by operating an AI knob or a mouse wheel when the magnification of the display setting is other than 100%.

Legacy Updates

V2.2.0 to V2.2.1

- Changed the system requirements to the following.
Intel Core i-series multicore processor 2 GHz or faster, or AMD equivalent processor

Yamaha Steinberg USB Driver

V1.10. to V2.0.3

- Solved a problem in which a blue screen error would occur when using the TF series.
- Fixed a problem in which USB Mode on the USB 3.0 model could not be switched while dspMixFx Remote Bridge was running.
- Fixed a problem in which Sound Forge (by Magix) would not work properly.
- Added Latency Mode setting in ASIO tab.
- Changed the launch method of the control panel. Launched by Start Menu→[Yamaha Steinberg USB Driver]→[Control Panel].
- Solved some minor problems.

Steinberg UR44 Applications

V2.2.0 to V2.2.1

Steinberg UR44 Extension

V2.1.0 to V2.1.1

- Now supports Yamaha Steinberg USB Driver V2.0.3.

Basic FX Suite

V1.1.1 to V1.1.2

- Solved a problem in which preset files used by other models were deleted when uninstalling.

V2.1.2 to V2.2.0

- Changed the system requirements to the following.
Cubase version 8.0 or later

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.9.9 to V1.10.3

- Fixed a problem in which noise might occur in the input/output when the ASIO buffer size was set to small value..
- Fixed a problem that application software would become unusable when recovering from sleep mode on a Modern Standby compatible PC.
- Now supports Yamaha MODX series.
- Solved a problem in which an application which uses Yamaha Steinberg USB Driver might be stopped when starting the application after a Windows update, etc.
- Solved a problem in which audio drop out may occur in some environments.
- Added a selection of 32 samples to the buffer size setting of the ASIO driver.
- Now supports Yamaha EAD10.
- Solved a problem in which noise may occur in a certain environment.
- Solved a problem in which a certain DAW software would terminate abnormally when switching the sample rate setting.
- Solved some other minor problems.

Steinberg UR44 Applications

V2.1.1 to V2.2.0

- Deleted the check for update function for dspMixFX.

Basic FX Suite

V1.0.1 to V1.1.1

- Improved the display in Windows 10.

V2.1.1 to V2.1.2

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.9.5 to V1.9.9

- Solved some minor problems on the UR22mkII.
- Solved a problem in which the Yamaha Steinberg USB Driver would not work in certain cases on the AUDIOGRAM/ MW/ MG/ IM series.
- Solved the following problems.
 - Audio loss may occur depending on the user environment.
 - Audio may distort after some period of time.
- Now supports Yamaha MONTAGE.
- Solved some minor problems.

V2.1.0 to V2.1.1

- Now supports Windows 10.

Yamaha Steinberg USB Driver

V1.8.5 to V1.9.5

Steinberg dspMixFx UR44

V2.1.0 to V2.1.1

The other main fixes and enhancements for each program are explained below.

Basic FX Suite

V1.0.0 to V1.0.1

- Solved some minor problems.

V2.0.0 to V2.1.0

- Now supports UR44 Firmware V2.10.

The other main fixes and enhancements for each program are explained below.

Steinberg UR44 Extension

V2.0.0 to V2.1.0

- Added the project templates for Cubase.

V1.0.1 to V2.0.0

- Added four Guitar Amp Classics effects to the DSP insert effect.
- ※Firmware V2.0.0 or later is required before using.

V1.0.0 to V1.0.1

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.8.2 to V1.8.3

- Now supports Windows 8.1.
- Solved some minor problems.

Company and product names that appear in this document are the trademarks or registered trademarks of their respective companies.

Manual Development Group
© 2013 Yamaha Corporation
Published 05/2021 YJHI-A0

TOOLS for UR44 V2.2.2 for Windows リリースノート

TOOLS for UR44 V2.2.2 for Windows は、以下のプログラムで構成されています。

- Yamaha Steinberg USB Driver V2.0.4
- Steinberg UR44 Applications V2.2.2
- Basic FX Suite V1.1.4

Steinberg UR44 Applications V2.2.2 は、以下のプログラムで構成されています。

- Steinberg UR44 Extension V2.1.1
- Steinberg dspMixFx UR44 V2.2.0

ソフトウェアの動作環境

NOTE

- お使いの OS によっては、下記の仕様以上の条件を満たす必要があります。

OS	Windows10(64-bit)
CPU	Intel Core i シリーズマルチコアプロセッサー2GHz 以上、または AMD 同等プロセッサー
メモリー	4 GB
画面解像度	1280 x 800 フルカラー
インターフェース	USB 端子を搭載していること
ハードディスク	1.2 GB 以上の空き容量、高速なハードディスク
その他	- UR44 ファームウェア:V2.10 以降 - Cubase との連携機能をお使いの場合、バージョン 9.0 以降の Cubase

主なアップデートの内容

V2.2.1 → V2.2.2

- 動作環境を変更しました。

その他の主なアップデート内容については、以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V2.0.3 → V2.0.4

- Yamaha YDS-150 に対応しました。
- 一部の Yamaha オーディオ機器で、DSD の再生ができない問題を修正しました。

Steinberg UR44 Applications

V2.2.1 → V2.2.2

- ディスプレイ設定の拡大率が 100%以外のときに、Cubase11 のインスペクター上で同梱プラグインのパラメーターが、マウスホイールの操作で変更できない場合がある問題を修正しました。

Basic FX Suite

V1.1.2 → V1.1.4

- FL Studio でプラグインをインサートすると、FL Studio が異常終了する問題を修正しました。
- ディスプレイ設定の拡大率が 100%以外のときに、Cubase11 上でプラグインのパラメーターが、AI ノブやマウスホイールの操作で正常に変更できない場合がある問題を修正しました。

過去のアップデートの内容

V2.2.0 → V2.2.1

- 動作環境を変更しました。以下の環境が必要です。
Intel Core i シリーズマルチコアプロセッサー2GHz 以上、または AMD 同等プロセッサー

Yamaha Steinberg USB Driver

V1.10.3 → V2.0.3

- TF シリーズを使用しているときに、ブルースクリーンエラーが発生する問題を修正しました。
- USB 3.0 モデルで、dspMixFx Remote Bridge 動作中に USB Mode を切り替えられない問題を修正しました。
- Magix 社 Sound Forge で正常に動作しない問題を修正しました。
- ASIO タブに Latency Mode 設定を追加しました。
- コントロールパネルの起動方法を変更しました。スタートメニュー→[Yamaha Steinberg USB Driver] →[Control Panel]で起動します。
- その他の軽微な不具合を修正しました。

Steinberg UR44 Applications

V2.2.0 → V2.2.1

Steinberg UR44 Extension

V2.1.0 → V2.1.1

- Yamaha Steinberg USB Driver V2.0.3 に対応しました。

Basic FX Suite

V1.1.1 → V1.1.2

- アンインストール時、他モデルで使用中のプリセットファイルが削除されてしまう問題を修正しました。

V2.1.2 → V2.2.0

- 動作環境を変更しました。以下の環境が必要です。
Cubase 8.0 以降

その他の主なアップデート内容について、以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.9.9 → V1.10.3

- ASIO バッファサイズを小さく設定したとき、入出力にノイズが混入することがある問題を修正しました。
- Modern Standby 対応の PC でスリープから復帰したとき、アプリケーションソフトが使用不能になる問題を修正しました。
- Yamaha MODX シリーズに対応しました。
- Windows アップデート後などに Yamaha Steinberg USB Driver を使用するアプリケーションを起動すると、アプリケーションが停止することがある問題を修正しました。
- 一部の環境でオーディオドロップアウトが発生する問題を修正しました。
- ASIO ドライバーのバッファサイズの設定値に、32 サンプルを追加しました。
- Yamaha EAD10 に対応しました。
- 特定の環境でノイズが発生する問題を修正しました。
- 特定の DAW ソフトウェアで使用している場合、サンプリング周波数を変更したときに DAW ソフトウェアが異常終了する問題を修正しました。
- その他の軽微な不具合を修正しました。

Steinberg UR44 Applications

V2.1.1 → V2.2.0

- dspMixFx の Check for Update 機能を削除しました。

Basic FX Suite

V1.0.1 → V1.1.1

- Windows 10 での表示を改善しました。

V2.1.1 → V2.1.2

主なアップデート内容について、以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.9.5 → V1.9.9

- UR22mkII での軽微な不具合を修正しました。
- AUDIOGRAM/ MW/ MG/ IM シリーズで動作しない場合がある問題を修正しました。
- 以下の問題への対策を行ないました。
 - ・お使いの環境によっては、音が途切れることがある。
 - ・ある一定時間を経過すると音が歪むことがある。
- Yamaha MONTAGE シリーズに対応しました。
- 軽微な不具合を修正しました。

V2.1.0 → V2.1.1

- Windows 10 に対応しました。

Yamaha Steinberg USB Driver

V1.8.5 → V1.9.5

Steinberg dspMixFx UR44

V2.1.0 → V2.1.1

その他の主なアップデート内容については、以下にプログラム別で説明します。

Basic FX Suite

V1.0.0 → V1.0.1

- 軽微な不具合を修正しました。

V2.0.0 → V2.1.0

- 本体ファームウェア V2.10 に対応しました。

その他の主なアップデート内容については、以下にプログラム別で説明します。

Steinberg UR44 Extension

V2.0.0 → V2.1.0

- Cubase 用のプロジェクトテンプレートを追加しました。

V1.0.1 → V2.0.0

- DSP インサートエフェクトに Guitar Amp Classics 4 種類を追加しました。
- ※ファームウェアを V2.0.0 以降にアップデートしてご使用ください。

V1.0.0 → V1.0.1

主なアップデート内容について、以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.8.2 → V1.8.3

- Windows 8.1 に対応しました。
- 軽微な不具合を修正しました。

本文に掲載されている会社名および商品名等は、各社の登録商標または商標です。

Manual Development Group
© 2013 Yamaha Corporation
2021 年 5 月 発行 YJHI-A0