

TOOLS for UR824 V2.2.1 for Mac Release Notes

TOOLS for UR824 V2.2.1 for Mac consists of the following programs.

- Yamaha Steinberg USB Driver V2.0.2
- Steinberg UR824 Applications V2.2.1
- Basic FX Suite V1.1.1

Steinberg UR824 Applications V2.2.1 consists of the following programs.

- Steinberg UR824 Extension V2.1.6
- Steinberg dspMixFx UR824 V2.2.1

System Requirements for Software

NOTE

- Note that the system requirements may be slightly different from those described below depending on the particular operating system.

OS	macOS 10.12.6, macOS 10.13.6, macOS 10.14.x, macOS 10.15.x
CPU	Intel multicore processor (Intel Core i5 or faster recommended)
Memory	2 GB or more
Interface	Equipped with a USB connector
Hard Disk	Free disk space of 1.2 GB or more; high-speed hard disk
Other	<ul style="list-style-type: none">- UR824 Firmware V2.10 or later- Cubase version 8.0 or later when using the link function between the device and Cubase.

Main Revisions and Enhancements

V2.2.0 to V2.2.1

- Now supports macOS 10.15.
- Changed the system requirements to the following.

macOS 10.12.6, macOS 10.13.6, macOS 10.14.x, macOS 10.15.x

Intel multicore processor (Intel Core i5 or faster recommended)

Yamaha Steinberg USB Driver

V1.10.2 to V2.0.2

- Solved a problem in which USB data transfer could not be completed in time and audio dropout would occur if a Mac with slower USB transfer spec was used with macOS 10.12 or

later.

- Changed the launch method of the control panel. Launched by [Application] → [Yamaha Steinberg USB Control Panel].
- Solved some minor problems.

Legacy Updates

V2.1.6 to V2.2.0

- Changed the system requirements to the following.
 - Mac OS X 10.11, macOS 10.12, macOS 10.13, macOS 10.14
 - Cubase version 8.0 or later

The other main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.9.10 to V1.10.2

- Now Supports Yamaha MODX series.

Steinberg UR824 Applications

V2.1.6 to V2.2.0

- Optimized the operation for 64-bit operating systems.
- Deleted the check for update function for dspMixFX.

Basic FX Suite

V1.0.1 to V1.1.0

- Added the AU Plug-ins.

V2.1.5 to V2.1.6

- Changed the system requirements to the following.

OS X 10.9.5/OS X 10.10.5/OS X 10.11.x/macOS 10.12.x/macOS 10.13.x

The other main fixes and enhancements for each program are explained below.

Steinberg UR824 Extension

V2.1.5 to V2.1.6

- Solved some minor problems.

V2.1.4 to V2.1.5

- Changed the system requirements to the following.
OS X 10.9.5/OS X 10.10.5/OS X 10.11.x/macOS 10.12.x

The other main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.9.8 to V1.9.10

- Now supports Yamaha MONTAGE series firmware V1.20.
- Solved some minor problems.
- Now supports Yamaha MONTAGE.

Steinberg UR824 Extension

V2.1.2 to V2.1.5

- Solved some minor problems.

Steinberg dspMixFx UR824

V2.1.2 to V2.1.5

- Solved some minor problems.

V2.1.3 to V2.1.4

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.9.6 to V1.9.8

- Improved audio input and output performance.
- Fixed a problem in which audio drop-outs would occur during both audio recording and playback on OS X 10.11.1.

V2.1.2 to V2.1.3

- Changed the system requirements to the following.
OS X 10.9.5/OS X 10.10.x/OS X 10.11.x

The other main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.9.4 to V1.9.6

- Now supports OS X 10.11.

V1.9.3 to V1.9.4

- Now supports Steinberg UR22mkII.
- Solved some minor problems.

V1.9.2 to V1.9.3

- Now supports Yamaha THR100H/THR100HD.

V2.1.0 to V2.1.2

- Changed the system requirements to the following.
OS X 10.7.5, OS X 10.8.5, OS X 10.9.x, or OS X 10.10.x

The other main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.8.5 to V1.9.2

- Now supports Yamaha AUDIOGRAM/ MW/ MG/ IM Series (USB-equipped model).
- Now supports Yamaha A-S801.
- Improved audio input and output performance.
- Now supports Yamaha MOXF series firmware V1.10.
- Solved some minor problems.

Steinberg UR824 Extension

V2.1.0 to V2.1.2

- Solved some minor problems.

Steinberg dspMixFx UR824

V2.1.0 to V2.1.2

- Solved some minor problems.

Basic FX Suite

V1.0.0 to V1.0.1

- Solved some minor problems.

V2.0.1 to V2.1.0

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.8.3 to V1.8.5

- Now supports UR824 Firmware V2.10.

Steinberg UR824 Extension

V2.0.0 to V2.1.0

- Now supports UR824 Firmware V2.10.
- Added the project templates for Cubase.

V2.0.0 to V2.0.1

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.8.1 to V1.8.3

- Now supports OS X 10.9.

V1.8.0 to V1.8.1

- Now supports Yamaha MOXF6/8.
- Solved some minor problems.

V1.5.0 to V2.0.0

- Added four Guitar Amp Classics effects to the DSP insert effect.
- Added the Loopback function.
- Restructured the VST Plug-ins as Basic FX Suite.
- Changed the system requirements to the following.

OS X 10.7.x or 10.8.x

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.7.3 to V1.8.0

- Now supports Yamaha CD-S3000

Steinberg UR824 Extension

V1.5.0 to V2.0.0

- Added the project templates for Cubase 7.

Steinberg dspMixFx UR824

V1.5.0 to V2.0.0

V1.0.6 to V1.5.0

- Added the 176.4 kHz and 192 kHz settings to the sample rate selection.
For details on setting the sample rate and limits regarding higher settings, refer to the latest manuals downloadable from the Steinberg website.
※UR824 Firmware V1.50 or later is required for use.

V1.0.5 to V1.0.6

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.7.2 to V1.7.3

- Added the 176.4 kHz and 192 kHz settings to the sample rate selection for Steinberg UR824.

V1.7.0 to V1.7.2

- Now supports Cubase 7.

V1.6.4 to V1.7.0

- Now supports Steinberg UR22.

NOTE

Yamaha Steinberg USB Driver V1.7.0 is the version which is included in the TOOLS for UR22 CD-ROM (labeled "YE968B0") in the Steinberg UR22 package.

V1.6.3 to V1.6.4

- Now supports Yamaha MX49/61.

Steinberg UR824 Extension

V1.0.4 to V1.0.6

Steinberg dspMixFx UR824

V1.0.5 to V1.0.6

- Now supports Cubase 7.

V1.0.4 to V1.0.5

- TOOLS for UR824 has been confirmed to work properly on OS X 10.8.
- The installer now supports Gatekeeper.
- An uninstaller function is included. For details about using it, refer to the included Installation Guide.

The other main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.6.0 to V1.6.3

- Solved some minor problems.

Steinberg dspMixFx UR824

V1.0.4 to V1.0.5

- Solved some minor problems.

V1.0.2 to V1.0.4

The main fixes and enhancements for each program are explained below.

Steinberg UR824 Extension

V1.0.1 to V1.0.4

- Now supports Cubase 6.5.

Steinberg dspMixFx UR824

V1.0.1 to V1.0.4

- Solved the problem in which the update program would not work properly without quitting the dspMixFx UR824 when updating the software version with "Check for Update" function on OS X 10.7.

V1.0.1 to V1.0.2

The main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.5.2 to V1.6.0

- Now supports Yamaha 01V96i.

To remove the Yamaha Steinberg USB Driver, delete the following files from the boot disk as well as the files described in the “Uninstalling the Software” section of the Getting Started document.

/Library/Audio/MIDI Devices/Yamaha/Images/

USB_1506.tiff
USB_1507.tiff
USB_5500.tiff

V1.0.0 to V1.0.1

- Now supports OS X 10.7.

The other main fixes and enhancements for each program are explained below.

Yamaha Steinberg USB Driver

V1.5.1 to V1.5.2

- Improved audio input and output performance.
- Solved the problem in which the Enable Power Management setting might not be displayed properly when opening the control panel of the driver on Mac OS X 10.6.8 or later (Mac OS X 10.6.7 or later on Mac with Thunderbolt port).

Steinberg UR824 Extension

V1.0.0 to V1.0.1

- Solved the problem in which the initial settings of the Channel Strip would be initialized on the undisturbed channels of increased/decreased channels by switching the sample rate.
- Solved the problem in which the Channel Strip might not work properly when switching the active project in Cubase.
- Solved the problems which would occur when both the UR824 Extension and the MR Extension were being installed. If you use the Steinberg MR816 CSX/MR816 X, download and install the TOOLS for MR V1.7.2 or later from the Steinberg web site.
- Solved some other minor problems.

Steinberg dspMixFx UR824

V1.0.0 to V1.0.1

- Solved some minor problems.

VST Plug-Ins

V1.0.0 to V1.0.1

- Solved some minor problems.

Company and product names that appear in this document are the trademarks or registered trademarks of their respective companies.

Manual Development Group
© 2011 Yamaha Corporation
Published 01/2020 YJTY-A0

TOOLS for UR824 V2.2.1 for Mac リリースノート

TOOLS for UR824 V2.2.1 for Mac は、以下のプログラムで構成されています。

- Yamaha Steinberg USB Driver V2.0.2
- Steinberg UR824 Applications V2.2.1
- Basic FX Suite V1.1.1

Steinberg UR824 Applications V2.2.1 は、以下のプログラムで構成されています。

- Steinberg UR824 Extension V2.1.6
- Steinberg dspMixFx UR824 V2.2.1

ソフトウェアの動作環境

NOTE

- お使いの OS によっては、下記の仕様以上の条件を満たす必要があります。

OS	macOS 10.12.6、macOS 10.13.6、macOS 10.14.x、macOS 10.15.x
CPU	Intel マルチコアプロセッサ (Intel Core i5 以上推奨)
メモリー	2 GB 以上
インターフェース	USB 端子を搭載していること
ハードディスク	1.2 GB 以上の空き容量、高速なハードディスク
その他	<ul style="list-style-type: none">UR824 のファームウェア: V2.10 以降Cubase との連携機能をお使いの場合、Cubase のバージョン 8.0 以降

主なアップデートの内容

V2.2.0 → V2.2.1

- macOS 10.15 に対応しました。
- 動作環境を変更しました。以下の環境が必要です。
macOS 10.12.6、macOS 10.13.6、macOS 10.14.x、macOS 10.15.x
Intel マルチコアプロセッサ (Intel Core i5 以上推奨)

Yamaha Steinberg USB Driver

V1.10.2 → V2.0.2

- USB 転送の遅い Mac を macOS 10.12 以降の新しい OS で使用した場合に、データ転送が間に合わずオーディオドロップアウトが発生する問題を修正しました。
- コントロールパネルの起動方法を変更しました。[アプリケーション] → [Yamaha Steinberg USB Control Panel]で起動します。
- その他の軽微な不具合を修正しました。

過去のアップデートの内容

V2.1.6 → V2.2.0

- 動作環境を変更しました。以下の環境が必要です。

Mac OS X 10.11/macOS 10.12/macOS 10.13/macOS 10.14

Cubase 8.0 以降

その他の主なアップデート内容については、以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.9.10 → V1.10.2

- Yamaha MODX シリーズに対応しました。

Steinberg UR824 Applications

V2.1.6 → V2.2.0

- 64-bit OS での動作を最適化しました。
- dspMixFx の Check for Update 機能を削除しました。

Basic FX Suite

V1.0.1 → V1.1.0

- AU プラグインを追加しました。

V2.1.5 → V2.1.6

- 動作環境を変更しました。以下の環境が必要です。

OS X 10.9.5/OS X 10.10.5/OS X 10.11.x/macOS 10.12.x/macOS 10.13.x

その他の主なアップデート内容については、以下にプログラム別で説明します。

Steinberg UR824 Extension

V2.1.5 → V2.1.6

- 軽微な不具合を修正しました。

V2.1.4 → V2.1.5

- 動作環境を変更しました。以下の環境が必要です。

OS X 10.9.5/OS X 10.10.5/OS X 10.11.x/macOS 10.12.x

その他の主なアップデート内容については、以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.9.8 → V1.9.10

- Yamaha MONTAGE シリーズ フームウェア V1.20 に対応しました。
- 軽微な不具合を修正しました。
- Yamaha MONTAGE シリーズに対応しました。

Steinberg UR824 Extension

V2.1.2 → V2.1.5

- 軽微な不具合を修正しました。

Steinberg dspMixFx UR824

V2.1.2 → V2.1.5

- 軽微な不具合を修正しました。

V2.1.3 → V2.1.4

主なアップデート内容については、以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.9.6 → V1.9.8

- オーディオ入出力のパフォーマンスを向上しました。
- OS X 10.11.1 環境で、オーディオ録音および再生時に音切れが発生する問題を修正しました。

V2.1.2 → V2.1.3

- 動作環境を変更しました。以下の環境が必要です。

OS X 10.9.5, OS X 10.10.x, OS X 10.11.x

その他の主なアップデート内容については、以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.9.4 → V1.9.6

- OS X 10.11 に対応しました。

V1.9.3 → V1.9.4

- Steinberg UR22mkII に対応しました。

- 軽微な不具合を修正しました。

V1.9.2 → V1.9.3

- Yamaha THR100H/THR100HD に対応しました。

V2.1.0 → V2.1.2

- 動作環境を変更しました。以下の環境が必要です。

OS X 10.7.5, OS X 10.8.5, OS X 10.9.x, OS X 10.10.x

その他の主なアップデート内容については、以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.8.5 → V1.9.2

- Yamaha AUDIOGRAM/MW/MG/IM シリーズの USB 搭載モデルに対応しました。
- Yamaha A-S801 に対応しました。
- オーディオ入出力のパフォーマンスを向上しました。
- Yamaha MOXF シリーズ フームウェア V1.10 に対応しました。
- 軽微な不具合を修正しました。

Steinberg UR824 Extension

V2.1.0 → V2.1.2

- 軽微な不具合を修正しました。

Steinberg dspMixFx UR824

V2.1.0 → V2.1.2

- 軽微な不具合を修正しました。

Basic FX Suite

V1.0.0 → V1.0.1

- 軽微な不具合を修正しました。

V2.0.1 → V2.1.0

その他の主なアップデート内容については、以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.8.3 → V1.8.5

- 本体ファームウェア V2.10 に対応しました。

Steinberg UR824 Extension

V2.0.0 → V2.1.0

- 本体ファームウェア V2.10 に対応しました。
- Cubase 用のプロジェクトテンプレートを追加しました。

V2.0.0 → V2.0.1

主なアップデート内容については、以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.8.1 → V1.8.3

- OS X 10.9 に対応しました。

V1.8.0 → V1.8.1

- Yamaha MOXF6/8 に対応しました。
- 軽微な不具合を修正しました。

V1.5.0 → V2.0.0

- DSP インサートエフェクトに Guitar Amp Classics 4 種類を追加しました。
- ループバック機能を追加しました。
- VST プラグインを Basic FX Suite として再構成しました。
- 動作環境を変更しました。以下の環境が必要です。

OS X 10.7.x または 10.8.x

その他の主なアップデート内容については、以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.7.3 → V1.8.0

- Yamaha CD-S3000 に対応しました。

Steinberg UR824 Extension

V1.5.0 → V2.0.0

- Cubase7 用のプロジェクトテンプレートを追加しました。

Steinberg dspMixFx UR824

V1.5.0 → V2.0.0

V1.0.6 → V1.5.0

- サンプリング周波数を 176.4 kHz/192 kHz に設定できるようになりました。
サンプリング周波数の切り替え方法や制限事項などの詳細は、スタインバーグのウェブサイトからダウンロードできる最新の取扱説明書をご参照ください。
※UR824 のファームウェアを V1.50 以降にアップデートしてご使用ください。

V1.0.5 → V1.0.6

以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.7.2 → V1.7.3

- Steinberg UR824 でサンプリング周波数を 176.4kHz/192kHz に設定できるようになりました。

V1.7.0 → V1.7.2

- Cubase 7 に対応しました。

V1.6.4 → V1.7.0

- Steinberg UR22 に対応しました。

NOTE

Yamaha Steinberg USB Driver V1.7.0 は、Steinberg UR22 に同梱の TOOLS for UR22 CD-ROM (盤面に「YE968B0」と記載されているもの)に収録されているバージョンです。

V1.6.3 → V1.6.4

- Yamaha MX49/61 に対応しました。

Steinberg UR824 Extension

V1.0.4 → V1.0.6

Steinberg dspMixFx UR824

V1.0.5 → V1.0.6

- Cubase 7 に対応しました。

V1.0.4 → V1.0.5

- TOOLS for UR824 が OS X 10.8 で動作することを確認しました。

- インストーラーが Gatekeeper に対応しました。
- アンインストーラーを同梱しました。使用方法は同梱のインストールガイドをご参照ください。

その他の主なアップデート内容については、以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.6.0 → V1.6.3

- 軽微な不具合を修正しました。

Steinberg dspMixFx UR824

V1.0.4 → V1.0.5

- 軽微な不具合を修正しました。

V1.0.2 → V1.0.4

以下にプログラム別で説明します。

Steinberg UR824 Extension

V1.0.1 → V1.0.4

- Cubase 6.5 に対応しました。

Steinberg dspMixFx UR824

V1.0.1 → V1.0.4

- OS X 10.7 で、Check for update 機能にてソフトウェアを新しいバージョンに更新するときに、dspMixFx UR824 が終了せずに、更新が正常に行えないことがある問題を修正しました。

V1.0.1 → V1.0.2

以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.5.2 → V1.6.0

- Yamaha 01V96i に対応しました。

Yamaha Steinberg USB Driver を削除する場合は、セットアップガイドのアンインストール方法に掲載しているファイルのほかに、次のファイルも起動ディスクから削除してください。

/Library/Audio/MIDI Devices/Yamaha/Images/

USB_1506.tif

USB_1507.tif

USB_5500.tiff

V1.0.0 → V1.0.1

- OS X 10.7 に対応しました。

その他の主なアップデート内容については、以下にプログラム別で説明します。

Yamaha Steinberg USB Driver

V1.5.1 → V1.5.2

- オーディオ入出力のパフォーマンスを向上しました。
- Mac OS X 10.6.8 以降(Thunderbolt 搭載の Mac は 10.6.7 以降)で使用した場合、ドライバーのコントロールパネルを開いたときに、Enable Power Management の設定が正しく表示されないことがある問題を修正しました。

Steinberg UR824 Extension

V1.0.0 → V1.0.1

- サンプリング周波数を変更して入出力のチャンネル数が変わったときに、増減したチャンネル以外のチャンネルの、Channel Strip の設定も初期化してしまう問題を修正しました。
- プロジェクトを切り替えたときに、Channel Strip が動作しないことがある問題を修正しました。
- MR Extension と UR824 Extension が共にインストールされている際に発生する問題を修正しました。Steinberg MR816 CSX/MR816 X をご使用の場合は、TOOLS for MR V1.7.2 以降を Steinberg のウェブサイトからダウンロードしてインストールしてください。
- その他軽微な不具合を修正しました。

Steinberg dspMixFx UR824

V1.0.0 → V1.0.1

- 軽微な不具合を修正しました。

VST Plug-Ins

V1.0.0 → V1.0.1

- 軽微な不具合を修正しました。

本文に掲載されている会社名および商品名等は、各社の登録商標または商標です。