

## **TOOLS for UR824 V2.2.2 for Windows Release Notes**

---

TOOLS for UR824 V2.2.2 for Windows consists of the following programs.

- Yamaha Steinberg USB Driver V2.0.4
- Steinberg UR824 Applications V2.2.1
- Basic FX Suite V1.1.4

Steinberg UR824 Applications V2.2.1 consists of the following programs.

- Steinberg UR824 Extension V2.1.6
- Steinberg dspMixFx UR824 V2.2.0

### **System Requirements for Software**

#### **NOTE**

- Note that the system requirements may be slightly different from those described below depending on the particular operating system.

OS	Windows10(64-bit)
CPU	Intel Core i-series multicore processor 2GHz or faster, or AMD equivalent processor
Memory	4 GB
Interface	Equipped with a USB connector
Hard Disk	Free disk space of 1.2 GB or more; high-speed hard disk
Other	<ul style="list-style-type: none"><li>- UR824 Firmware V2.10 or later</li><li>- Cubase 9.0 or later when using the link function between the device and Cubase.</li></ul>

### **Main Revisions and Enhancements**

#### **V2.2.1 to V2.2.2**

- Changed the system requirements.

The main fixes and enhancements for each program are explained below.

#### **Yamaha Steinberg USB Driver**

V2.0.3 to V2.0.4

- Now supports Yamaha YDS-150.
- Fixed a problem in which DSD could not be played back with some Yamaha audio devices.

## **Steinberg UR824 Applications**

V2.2.0 to V2.2.1

- Fixed a problem in which the parameter of the bundled plug-in on the Cubase 11 Inspector panel may not be changed by operating a mouse wheel when the magnification of the display setting is other than 100%.

## **Basic FX Suite**

V1.1.2 to V1.1.4

- Solved a problem in which FL Studio would terminate abnormally when a plug-in was inserted in FL Studio.
- Fixed a problem in which a plug-in parameter in Cubase 11 may not be changed properly by operating an AI knob or a mouse wheel when the magnification of the display setting is other than 100%.

## **Legacy Updates**

### **V2.2.0 to V2.2.1**

- Changed the system requirements to the following.  
Intel Core i-series multicore processor 2GHz or faster, or AMD equivalent processor

The main fixes and enhancements for each program are explained below.

## **Yamaha Steinberg USB Driver**

V1.10.3 to V2.0.3

- Solved a problem in which a blue screen error would occur when using the TF series.
- Fixed a problem in which USB Mode on the USB 3.0 model could not be switched while dspMixFx Remote Bridge was running.
- Fixed a problem in which Sound Forge (by Magix) would not work properly.
- Added Latency Mode setting in ASIO tab.
- Changed the launch method of the control panel. Launched by Start Menu→[Yamaha Steinberg USB Driver]→[Control Panel].
- Solved some minor problems.

## **Basic FX Suite**

V1.1.1 to V1.1.2

- Solved a problem in which preset files used by other models were deleted when uninstalling.

## **V2.1.6 to V2.2.0**

- Changed the system requirements to the following.  
Cubase 8.0 version or later

The main fixes and enhancements for each program are explained below.

### **Yamaha Steinberg USB Driver**

V1.9.11 to V1.10.3

- Fixed a problem in which noise might occur in the input/output when the ASIO buffer size was set to small value..
- Fixed a problem that application software would become unusable when recovering from sleep mode on a Modern Standby compatible PC.
- Now supports Yamaha MODX series.
- Solved a problem in which an application which uses Yamaha Steinberg USB Driver might be stopped when starting the application after a Windows update, etc.
- Solved a problem in which audio drop out may occur in some environments.
- Solved a problem in which noise may occur in a certain environment.
- Added a selection of 32 samples to the buffer size setting of the ASIO driver.
- Solved some other minor problems.

### **Steinberg UR824 Applications**

V2.1.6 to V2.2.0

- Deleted the check for update function for dspMixFX.

### **Basic FX Suite**

V1.0.1 to V1.1.1

- Improved the display in Windows 10.

## **V2.1.5 to V2.1.6**

The main fixes and enhancements for each program are explained below.

### **Yamaha Steinberg USB Driver**

V1.9.9 to V1.9.11

- Now supports Yamaha EAD10.

### **Steinberg UR824 Extension**

V2.1.5 to V2.1.6

- Solved some minor problems.

### **V2.1.4 to V2.1.5**

The main fixes and enhancements for each program are explained below.

### **Steinberg UR824 Extension**

V2.1.2 to V2.1.5

- Solved some minor problems.

### **V2.1.3 to V2.1.4**

The main fixes and enhancements for each program are explained below.

### **Yamaha Steinberg USB Driver**

V1.9.5 to V1.9.9

- Solved some minor problems on the UR22mkII.
- Solved a problem in which the Yamaha Steinberg USB Driver would not work in certain cases on the AUDIOGRAM/ MW/ MG/ IM series.
- Solved the following problems.
  - Audio loss may occur depending on the user environment.
  - Audio may distort after some period of time.
- Now supports Yamaha MONTAGE.
- Solved some minor problems.

### **V2.1.2 to V2.1.3**

Now supports Windows 10.

### **Yamaha Steinberg USB Driver**

V1.9.2 to V1.9.5

### **Steinberg dspMixFx UR824**

V2.1.0 to V2.1.3

### **V2.1.1 to V2.1.2**

The main fixes and enhancements for each program are explained below.

### **Yamaha Steinberg USB Driver**

V1.8.6 to V1.9.2

- Now supports Yamaha AG Series.
- Now supports Yamaha A-S801.
- Solved some minor problems.

### **Steinberg UR824 Extension**

V2.1.0 to V2.1.2

- Solved some minor problems.

### **Basic FX Suite**

V1.0.0 to V1.0.1

- Solved some minor problems.

### **V2.1.0 to V2.1.1**

The main fixes and enhancements for each program are explained below.

### **Yamaha Steinberg USB Driver**

V1.8.5 to V1.8.6

- Now supports Yamaha AUDIOGRAM/ MW/ MG/ IM Series (USB-equipped model).

#### **NOTE**

If the Yamaha USB Audio Driver is already installed on your computer, be sure to uninstall it before installing Yamaha Steinberg USB Driver. There is a possibility that the Yamaha Steinberg USB Driver will not work properly if the Yamaha USB Audio Driver is installed on the same computer.

- Now supports Yamaha MOXF Series firmware V1.10.
- Solved some minor problems.

### **V2.0.1 to V2.1.0**

- Now supports UR824 Firmware V2.10.

The other main fixes and enhancements for each program are explained below.

### **Yamaha Steinberg USB Driver**

V1.8.4 to V1.8.5

- Now supports UR824 Firmware V2.10.

V1.8.3 to V1.8.4

- Now supports Yamaha MG Series (XU Models).

### **Steinberg UR824 Extension**

V2.0.0 to V2.1.0

- Added the project templates for Cubase.

### **V2.0.0 to V2.0.1**

The main fixes and enhancements for each program are explained below.

### **Yamaha Steinberg USB Driver**

V1.8.1 to V1.8.3

- Now supports Windows 8.1.
- Solved some minor problems.

V1.8.0 to V1.8.1

- Now supports Yamaha MOXF6/8.
- Solved some minor problems.

### **V1.5.0 to V2.0.0**

- Added four Guitar Amp Classics effects to the DSP insert effect.
- Added the Loopback function.
- Restructured the VST Plug-ins as Basic FX Suite.
- Changed the system requirements to the following.  
Windows 7 or Windows 8

The main fixes and enhancements for each program are explained below.

### **Yamaha Steinberg USB Driver**

V1.7.3 to V1.8.0

- Now supports Yamaha CD-S3000
- ASIO Driver supports devices which use 32-bit sample format.

- Solved some minor problems.

### **Steinberg UR824 Extension**

V1.5.0 to V2.0.0

- Added the project templates for Cubase 7.

### **Steinberg dspMixFx UR824**

V1.5.0 to V2.0.0

### **V1.0.6 to V1.5.0**

- Added the 176.4 kHz and 192 kHz settings to the sample rate selection.  
For details on setting the sample rate and limits regarding higher settings, refer to the latest manuals downloadable from the Steinberg website.  
※UR824 Firmware V1.50 or later is required for use.

The other main fixes and enhancements for each program are explained below.

### **Yamaha Steinberg USB Driver**

V1.7.2 to V1.7.3

- Fixed a problem in which noise would occur during audio playback with the WDM.

### **V1.0.5 to V1.0.6**

The main fixes and enhancements for each program are explained below.

### **Yamaha Steinberg USB Driver**

V1.7.1 to V1.7.2

- Now supports Cubase 7.
- Solved some minor problems.

V1.6.5 to V1.7.1

- Now supports Steinberg UR22.

### **NOTE**

Yamaha Steinberg USB Driver V1.7.1 is the version which is included in the TOOLS for UR22 CD-ROM (labeled "YE968B0") in the Steinberg UR22 package.

### **Steinberg UR824 Extension**

V1.0.4 to V1.0.6

### **Steinberg dspMixFx UR824**

V1.0.5 to V1.0.6

- Now supports Cubase 7.

### **V1.0.4 to V1.0.5**

- TOOLS for UR824 has been confirmed to work properly on Windows 8.

The other main fixes and enhancements for each program are explained below.

### **Yamaha Steinberg USB Driver**

V1.6.4 to V1.6.5

- Solved some minor problems.

V1.6.3 to V1.6.4

- Now supports Yamaha MX49/61.
- Solved some minor problems.

V1.6.2 to V1.6.3

- Solved a problem in which the specified DAW software would not quit when switching the sample rate setting.
- Solved some other minor problems.

### **Steinberg dspMixFx UR824**

V1.0.4 to V1.0.5

- Solved some minor problems.

### **V1.0.3 to V1.0.4**

The main fixes and enhancements for each program are explained below.

### **Yamaha Steinberg USB Driver**

V1.6.1 to V1.6.2

- Improved the performance.



### **Steinberg UR824 Extension**

V1.0.1 to V1.0.4

- Now supports Cubase 6.5.

### **Steinberg dspMixFx UR824**

V1.0.1 to V1.0.4

- Solved the problem in which the update program would not work properly with the "Program Compatibility Assistant" dialog, which appears when updating the version of the software and the firmware of the device with the "Check for Update" function on Windows Vista or Windows 7.

### **V1.0.2 to V1.0.3**

The main fixes and enhancements for each program are explained below.

### **Yamaha Steinberg USB Driver**

V1.6.0 to V1.6.1

- Solved a problem related to computers equipped with certain AMD brand CPUs, in which noise might occur in the audio input signal when using the device with such a computer.

### **Steinberg UR824 Applications**

V1.0.1 to V1.0.2

- Solved the problem in which certain files would not be properly replaced by new ones when updating the TOOLS for UR824 from V1.0.0.

### **V1.0.1 to V1.0.2**

The main fixes and enhancements for each program are explained below.

### **Yamaha Steinberg USB Driver**

V1.5.2 to V1.6.0

- Now supports Yamaha 01V96i.
- Solved the problem in which the audio input/output might stop when switching the sample rate in the Cubase project setup.
- Solved some other minor problems

### **V1.0.0 to V1.0.1**

The main fixes and enhancements for each program are explained below.

### **Yamaha Steinberg USB Driver**

V1.5.1 to V1.5.2

- Solved some minor problems.

### **Steinberg UR824 Extension**

V1.0.0 to V1.0.1

- Solved the problem in which the initial settings of the Channel Strip would be initialized on the undisturbed channels of increased/decreased channels by switching the sample rate.
- Solved the problem in which the Channel Strip might not work properly when switching the active project in Cubase.
- Solved the problems which would occur when both the UR824 Extension and the MR Extension were being installed. If you use the Steinberg MR816 CSX/MR816 X, download and install the TOOLS for MR V1.7.2 or later from the Steinberg web site.
- Solved some other minor problems.

### **Steinberg dspMixFx UR824**

V1.0.0 to V1.0.1

- Solved some minor problems.

### **VST Plug-Ins**

V1.0.0 to V1.0.1

- Solved some minor problems.

---

Company and product names that appear in this document are the trademarks or registered trademarks of their respective companies.

## TOOLS for UR824 V2.2.2 for Windows リリースノート

---

TOOLS for UR824 V2.2.2 for Windows は、以下のプログラムで構成されています。

- Yamaha Steinberg USB Driver V2.0.4
- Steinberg UR824 Applications V2.2.1
- Basic FX Suite V1.1.4

Steinberg UR824 Applications V2.2.1 は、以下のプログラムで構成されています。

- Steinberg UR824 Extension V2.1.6
- Steinberg dspMixFx UR824 V2.2.0

### ソフトウェアの動作環境

#### NOTE

- お使いの OS によっては、下記の仕様以上の条件を満たす必要があります。

OS	Windows10(64-bit)
CPU	Intel Core i シリーズマルチコアプロセッサ2GHz 以上、または AMD 同等プロセッサ
メモリー	4 GB
インターフェース	USB 端子を搭載していること
ハードディスク	1.2 GB 以上の空き容量、高速なハードディスク
その他	・UR824 のファームウェア: V2.10 以降 ・Cubase との連携機能をお使いの場合、バージョン 9.0 以降の Cubase

### 主なアップデートの内容

#### V2.2.1 → V2.2.2

- 動作環境を変更しました。

その他の主なアップデート内容については、以下にプログラム別で説明します。

#### Yamaha Steinberg USB Driver

##### V2.0.3 → V2.0.4

- Yamaha YDS-150 に対応しました。
- 一部の Yamaha オーディオ機器で、DSD の再生ができない問題を修正しました。

## Steinberg UR824 Applications

V2.2.0 → V2.2.1

- ディスプレイ設定の拡大率が 100%以外のときに、Cubase 11 のインスペクター上で同梱プラグインのパラメーターが、マウスホイールの操作で変更できない場合がある問題を修正しました。

## Basic FX Suite

V1.1.2 → V1.1.4

- FL Studio でプラグインをインサートすると、FL Studio が異常終了する問題を修正しました。
- ディスプレイ設定の拡大率が 100%以外のときに、Cubase 11 上でプラグインのパラメーターが、AI ノブやマウスホイールの操作で正常に変更できない場合がある問題を修正しました。

## 過去のアップデートの内容

### V2.2.0 → V2.2.1

- 動作環境を変更しました。以下の環境が必要です。  
Intel Core i シリーズマルチコアプロセッサ 2GHz 以上、または AMD 同等プロセッサ

その他の主なアップデート内容については、以下にプログラム別で説明します。

## Yamaha Steinberg USB Driver

V1.10.3 → V2.0.3

- TF シリーズを使用しているときに、ブルースクリーンエラーが発生する問題を修正しました。
- USB 3.0 モデルで、dspMixFx Remote Bridge 動作中に USB Mode を切り替えられない問題を修正しました。
- Magix 社 Sound Forge で正常に動作しない問題を修正しました。
- ASIO タブに Latency Mode 設定を追加しました。
- コントロールパネルの起動方法を変更しました。スタートメニュー→[Yamaha Steinberg USB Driver] →[Control Panel]で起動します。
- その他の軽微な不具合を修正しました。

## Basic FX Suite

V1.1.1 → V1.1.2

- アンインストール時、他モデルで使用中のプリセットファイルが削除されてしまう問題を修正しました。

## **V2.1.6 → V2.2.0**

- 動作環境を変更しました。以下の環境が必要です。  
Cubase 8.0 以降

その他の主なアップデート内容については、以下にプログラム別で説明します。

### **Yamaha Steinberg USB Driver**

V1.9.11 → V1.10.3

- ASIO バッファサイズを小さく設定したとき、入出力にノイズが混入することがある問題を修正しました。
- Modern Standby 対応の PC でスリープから復帰したとき、アプリケーションソフトが使用不能になる問題を修正しました。
- Yamaha MODX シリーズに対応しました。
- Windows アップデート後などに Yamaha Steinberg USB Driver を使用するアプリケーションを起動すると、アプリケーションが停止することがある問題を修正しました。
- 一部の環境でオーディオドロップアウトが発生する問題を修正しました。
- 特定の環境でノイズが発生する問題を修正しました。
- ASIO ドライバーのバッファサイズの設定値に、32 サンプルを追加しました。
- その他の軽微な不具合を修正しました。

### **Steinberg UR824 Applications**

V2.1.6 → V2.2.0

- dspMixFx の Check for Update 機能を削除しました。

### **Basic FX Suite**

V1.0.1 → V1.1.1

- Windows 10 での表示を改善しました。

## **V2.1.5 → V2.1.6**

主なアップデート内容については、以下にプログラム別で説明します。

### **Yamaha Steinberg USB Driver**

V1.9.9 → V1.9.11

- Yamaha EAD10 に対応しました。

### **Steinberg UR824 Extension**

V2.1.5 → V2.1.6

- 軽微な不具合を修正しました。

### **V2.1.4 → V2.1.5**

主なアップデート内容については、以下にプログラム別で説明します。

#### **Steinberg UR824 Extension**

V2.1.2 → V2.1.5

- 軽微な不具合を修正しました。

### **V2.1.3 → V2.1.4**

主なアップデート内容については、以下にプログラム別で説明します。

#### **Yamaha Steinberg USB Driver**

V1.9.5 → V1.9.9

- UR22mkII での軽微な不具合を修正しました。
- AUDIOGRAM/ MW/ MG/ IM シリーズで動作しない場合がある問題を修正しました。
- 以下の問題への対策を行ないました。
  - ・お使いの環境によっては、音が途切れることがある。
  - ・ある一定時間を経過すると音が歪むことがある。
- Yamaha MONTAGE シリーズに対応しました。
- 軽微な不具合を修正しました。

### **V2.1.2 → V2.1.3**

- Windows 10 に対応しました。

#### **Yamaha Steinberg USB Driver**

V1.9.2 → V1.9.5

#### **Steinberg dspMixFx UR824**

V2.1.0 → V2.1.3

### **V2.1.1 → V2.1.2**

主なアップデート内容については、以下にプログラム別で説明します。

#### **Yamaha Steinberg USB Driver**

V1.8.6 → V1.9.2

- Yamaha AG シリーズに対応しました。
- Yamaha A-S801 に対応しました。
- 軽微な不具合を修正しました。

#### **Steinberg UR824 Extension**

V2.1.0 → V2.1.2

- 軽微な不具合を修正しました。

#### **Basic FX Suite**

V1.0.0 → V1.0.1

- 軽微な不具合を修正しました。

#### **V2.1.0 → V2.1.1**

主なアップデート内容については、以下にプログラム別で説明します。

#### **Yamaha Steinberg USB Driver**

V1.8.5 → V1.8.6

- Yamaha AUDIOGRAM/ MW/ MG/ IM シリーズの USB 搭載モデルに対応しました。

#### **NOTE**

Yamaha USB Audio Driver がコンピューターにインストールされている場合は、アンインストールしてから Yamaha Steinberg USB Driver をインストールしてください。同時にインストールされている場合、Yamaha Steinberg USB Driver が使用できない場合があります。

- Yamaha MOXF シリーズ ファームウェア V1.10 に対応しました。
- 軽微な不具合を修正しました。

#### **V2.0.1 → V2.1.0**

- 本体ファームウェア V2.10 に対応しました。

その他の主なアップデート内容については、以下にプログラム別で説明します。

#### **Yamaha Steinberg USB Driver**

V1.8.4 → V1.8.5

- 本体ファームウェア V2.10 に対応しました。

V1.8.3 → V1.8.4

- Yamaha MG シリーズ(XU モデル)に対応しました。

### **Steinberg UR824 Extension**

V2.0.0 → V2.1.0

- Cubase 用のプロジェクトテンプレートを追加しました。

### **V2.0.0 → V2.0.1**

主なアップデート内容については、以下にプログラム別で説明します。

#### **Yamaha Steinberg USB Driver**

V1.8.1 → V1.8.3

- Windows 8.1 に対応しました。
- 軽微な不具合を修正しました。

V1.8.0 → V1.8.1

- Yamaha MOXF6/8 に対応しました。
- 軽微な不具合を修正しました。

### **V1.5.0 → V2.0.0**

- DSP インサートエフェクトに Guitar Amp Classics 4 種類を追加しました。
- ループバック機能を追加しました。
- VST プラグインを Basic FX Suite として再構成しました。
- 動作環境を変更しました。以下の環境が必要です。

Windows 7 SP1 または Windows 8

その他の主なアップデート内容については、以下にプログラム別で説明します。

#### **Yamaha Steinberg USB Driver**

V1.7.3 → V1.8.0

- Yamaha CD-S3000 に対応しました。
- ASIO ドライバーが、32bit のサンプルフォーマットを使用する機器に対応しました。
- 軽微な不具合を修正しました。

### **Steinberg UR824 Extension**

V1.5.0 → V2.0.0



- Cubase7 用のプロジェクトテンプレートを追加しました。

#### **Steinberg dspMixFx UR824**

V1.5.0 → V2.0.0

#### **V1.0.6 → V1.5.0**

- サンプリング周波数を 176.4 kHz/192 kHz に設定できるようになりました。  
サンプリング周波数の切り替え方法や制限事項などの詳細は、スタインバーグのウェブサイトからダウンロードできる最新の取扱説明書をご参照ください。  
※UR824 のファームウェアを V1.50 以降にアップデートしてご使用ください。

その他の主なアップデート内容については、以下にプログラム別で説明します。

#### **Yamaha Steinberg USB Driver**

V1.7.2 → V1.7.3

- WDM を利用してオーディオを再生した場合、ノイズが発生することがある問題を修正しました。

#### **V1.0.5 → V1.0.6**

以下にプログラム別で説明します。

#### **Yamaha Steinberg USB Driver**

V1.7.1 → V1.7.2

- Cubase 7 に対応しました。
- 軽微な不具合を修正しました。

V1.6.5 → V1.7.1

- Steinberg UR22 に対応しました。

#### **NOTE**

Yamaha Steinberg USB Driver V1.7.1 は、Steinberg UR22 に同梱の TOOLS for UR22 CD-ROM (盤面に「YE968B0」と記載されているもの)に収録されているバージョンです。

#### **Steinberg UR824 Extension**

V1.0.4 → V1.0.6

#### **Steinberg dspMixFx UR824**

V1.0.5 → V1.0.6

- Cubase 7 に対応しました。

### **V1.0.4 → V1.0.5**

- TOOLS for UR824 が Windows 8 で動作することを確認しました。

その他の主なアップデート内容については、以下にプログラム別で説明します。

#### **Yamaha Steinberg USB Driver**

V1.6.4 → V1.6.5

- 軽微な不具合を修正しました。

V1.6.3 → V1.6.4

- Yamaha MX49/61 に対応しました。
- 軽微な不具合を修正しました。

V1.6.2 → V1.6.3

- 特定の DAW ソフトウェアで使用している場合、サンプリング周波数などの設定を変更したときに DAW ソフトウェアが終了できなくなる問題を修正しました。
- その他の軽微な不具合を修正しました。

#### **Steinberg dspMixFx UR824**

V1.0.4 → V1.0.5

- 軽微な不具合を修正しました。

### **V1.0.3 → V1.0.4**

以下にプログラム別で説明します。

#### **Yamaha Steinberg USB Driver**

V1.6.1 → V1.6.2

- パフォーマンスを改善しました。

#### **Steinberg UR824 Extension**

V1.0.1 → V1.0.4

- Cubase 6.5 に対応しました。

### **Steinberg dspMixFx UR824**

V1.0.1 → V1.0.4

- Windows Vista または Windows 7 で、Check for update 機能にてソフトウェアや本体のファームウェアを新しいバージョンに更新するときに、「プログラム互換性アシスタント」ダイアログが表示され、更新が正常に行えないことがある問題を修正しました。

### **V1.0.2 → V1.0.3**

以下にプログラム別で説明します。

#### **Yamaha Steinberg USB Driver**

V1.6.0 → V1.6.1

- AMD 社製の一部の CPU を搭載したコンピューターで使用したときに、オーディオの入力にノイズが発生することがある問題を修正しました。

#### **Steinberg UR824 Applications**

V1.0.1 → V1.0.2

- TOOLS for UR824 V1.0.0 からアップデートしたときに、一部のファイルが新しいものに差し替わらない問題を修正しました。

### **V1.0.1 → V1.0.2**

以下にプログラム別で説明します。

#### **Yamaha Steinberg USB Driver**

V1.5.2 → V1.6.0

- Yamaha 01V96i に対応しました。
- Cubase のプロジェクト設定でサンプリング周波数を切り替えると、オーディオ入出力が止まることある問題を修正しました。
- その他の軽微な不具合を修正しました。

### **V1.0.0 → V1.0.1**

以下にプログラム別で説明します。

#### **Yamaha Steinberg USB Driver**

V1.5.1 → V1.5.2

- 軽微な不具合を修正しました。

## **Steinberg UR824 Extension**

V1.0.0 → V1.0.1

- サンプリング周波数を変更して入出力のチャンネル数が変わったときに、増減したチャンネル以外のチャンネルの、Channel Strip の設定も初期化してしまう問題を修正しました。
- プロジェクトを切り替えたときに、Channel Strip が動作しないことがある問題を修正しました。
- MR Extension と UR824 Extension が共にインストールされている際に発生する問題を修正しました。Steinberg MR816 CSX/MR816 X をご使用の場合は、TOOLS for MR V1.7.2 以降を Steinberg のウェブサイトからダウンロードしてインストールしてください。
- その他軽微な不具合を修正しました。

## **Steinberg dspMixFx UR824**

V1.0.0 → V1.0.1

- 軽微な不具合を修正しました。

## **VST Plug-Ins**

V1.0.0 → V1.0.1

- 軽微な不具合を修正しました。

---

本文に掲載されている会社名および商品名等は、各社の登録商標または商標です。