

Yamaha USB-MIDI Driver V1.5.0 for Mac Release Notes

System Requirements for Software

NOTE

- Note that the system requirements may be slightly different from those described below depending on the particular operating system.
- Note that the operating system and interface may be different from those described below depending on the product. For details, refer to the particular operation manual and website for each product.

OS	macOS 11.x
CPU	Intel multi-core processor, or Apple silicon, with Rosetta 2 installed
Memory	4 GB or more
Interface	Equipped with a USB connector
Hard Disk	Free disk space of 2 MB or more; high-speed hard disk

Main Revisions and Enhancements

V1.3.2 → V1.5.0

- Now supports macOS 11.
- Changed the system requirements to the following.
macOS 11.x (Intel or Apple silicon, with Rosetta 2)

Previous Updates

V1.3.1 → V1.3.2

- Now supports Mac OS X 10.8.

V1.3.0 → V1.3.1

- An uninstaller function is included. For details about using it, refer to the included Installation Guide.
- Changed the function in which the "Old style port name" checkbox works when "YAMAHA USB-MIDI Control Panel" under "System Preferences" is active. For details about this function, refer to the included Installation Guide.
- Solved some minor problems.

V1.2.2 → V1.3.0

- Now supports Mac OS X 10.7.
- Now supports 64-bit native.
- Modified the installer to display “Software License Agreement” while installing.
- Minor bug fixes.

V1.2.1 to V1.2.2

- Minor bug fixes.

V1.2.0 to V1.2.1

- Now supports Mac OS X 10.6.
- Changed the specification so that the driver now supports Mac OS X 10.4.11 or later.
- Minor bug fixes.

V1.1.1 to V1.2.0

- Changed the specification so that MIDI Port names did not show any device names.
- The MIDI Patch function and the MIDI Thru function have been removed.
- Minor bug fixes.

V1.1.0 to V1.1.1

- A problem in which the driver did not operate properly in some language environments has been corrected.
- Minor bug fixes.

V1.0.4 to V1.1.0

- Support for Macintosh computers using Intel processors has been added.

V1.0.3 to V1.0.4

- Problems in which the MIDI driver occasionally hangs up during transmission and reception of MIDI data when using a dual CPU Macintosh have been corrected.

V1.0.1 to V1.0.3

- Handling of system exclusive message errors has been improved.

V1.0.0 to V1.0.1

- Problems in opening the audio port of the UW500/UW10 when using Emagic Logic have been corrected.

V1.0.0b1 to V1.0.0

- Design of icons has been changed.

Company and product names that appear in this document are the trademarks or registered trademarks of their respective companies.

(C) 2009-2021 Yamaha Corporation All Rights Reserved.